

County Surveyor's Record, Douglas County, Oregon

18123 Dependent Resurvey, Portion of Subdivisional Lines,
T. 24 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

Ascend over S. slope, through heavy timber and dense undergrowth.

3.40 Gravel road, 30 lks wide, bears N. 70° E. and S. 70° W.

7.60 Ridge, bears E. and W.; desc. over broken NE. slope.

24.40 Creek, 2 lks. wide, curse, NE.; asc. over SE. slope.

29.50 Spur. slopes NE.; desc. over N. slope.

36.90 Ravine, drains S. 70° E.; asc. over broken NE. slope.

39.30 Top of ascent, slopes NE.; desc. over NW. slope.

39.95 Point for the $\frac{1}{4}$ sec. cor. of secs. 34 and 35, at proportionate dist.; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 24 S R 8 W
 $\frac{1}{4}$
S 34 | S 35
1986

from which

A cedar, 15 ins. diam., bears N. 50° E., 18 lks. dist., mkd. $\frac{1}{4}$ S35 BT.

A fir, 13 ins. diam., bears S. 76° W., 32 lks. dist., mkd. $\frac{1}{4}$ S34 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Continue over NW. slope.

41.70 Abandoned road, 30 lks. wide, bears NW. and SE.

53.30 Begin descent over steep NW. slope.

62.90 Creek, 5 lks. wide, course N. 70° E.; asc. over broken SE slope.

78.20 Spur, slopes NE.; desc. over NW. slope.

79.90 The cor. of secs. 26, 27, 34, and 35, monumented with an iron post, 2 $\frac{1}{2}$ ins. diam., firmly set, projecting 5 ins. above ground, with brass cap mkd.

T 24 S R 8 W
S 27 | S 26
S 34 | S 35
1959

from which the remains of the original bearing trees

A fir snag, 45 ins. diam., bears S. 12° E., 23 lks. dist., with axe marks on a burned blaze. (Record, 50 ins. diam., 26 lks.)

A fir snag, 47 ins. diam., bears S. 28° W., 31 lks. dist., with opened and decayed blaze.