

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **18124**
T. 24 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears N. 81° W., 68 lks. dist., with a decayed fir, 20 ins. diam., lying alongside with scribe marks W S visible on opened blaze.

and the remains of bearing trees mkd. by Corbin

A hemlock, 15 ins. diam., bears N. 34° E., 33 lks. dist., with scribe marks R8W S26 visible on partially healed blaze.

A hemlock, 12 ins. diam., bears S. 76° E., 30 lks. dist., with healed blaze.

A hemlock snag, 12 ins. diam., bears S. 13½° W., 104 lks. dist., with healed blaze.

and two new bearing trees

A fir, 7 ins. diam., bears S. 47° W., 20 lks. dist., mkd. T24S R8W S34 BT.

A cedar, 8 ins. diam., bears N. 38° W., 28 lks. dist., mkd. T24S R8W S27 BT.

From the cor. of secs. 25, 26, 35, and 36.

N. 89° 24' W., bet. secs. 26 and 35.

Descend over a broken SW. slope, through heavy timber and dense undergrowth.

- 5.30 Gravel road, 30 lks. wide, bears N. 30° E. and S. 30° W.
 - 13.00 Dirt road, 10 lks. wide, bears N. 20° W. and S. 20° E., at bottom of descent; cross creek bottom land.
 - 17.30 Wolf Creek, 60 lks. wide, course S. 10° E.; asc. over a steep E. slope.
 - 19.10 Asphalt road, 30 lks. wide, bears N. 20° W., and S. 20° E.
 - 21.50 Spur, slopes S.; desc. over SW. slope.
 - 25.30 Gravel road, 30 lks. wide, bears NW. and SE.
 - 35.90 Miner Creek, 20 lks. wide, course S. 20° E.; asc. over NE. slope.
 - 38.10 Spur, slopes N.; desc. over NW. slope.
 - 40.35 The ¼ sec. cor. of secs. 26 and 35, determined from the remaining original bearing tree:
 - A cedar, 35 ins. diam., bears S. 40° E., 58 lks. dist., no marks visible on an opened and decayed blaze and with an old metal tag embedded in overgrowth. The tag is mkd. GLO T24S R8W ¼ COR.
- At the corner point
- Set a stainless steel post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.