

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the East Boundary, **18138**
T. 31 S., R 4 W., Willamette Meridian, Oregon

CHAINS	
	Ascend over SW. slope, through heavy timber and dense undergrowth.
8.60	Spur, slopes S. 80° W.; desc. over broken NW. slope
37.10	Spur, slopes N. 50° W.; desc. over NE. slope.
39.79	<p>The $\frac{1}{4}$ sec. cor. of secs. 1 and 6, perpetuated and recorded by John H. Markham, Jr., Registered Engineer No. 2880, in 1960, monumented with the original stone, 16 x 14 x 12 ins. loosely set, projecting 10 ins. above ground, no marks visible, (alongside of which is an iron pipe, $\frac{1}{2}$ in. diam., firmly set, projecting 10 ins. above ground,) from which the remains of the original bearing trees:</p> <p style="margin-left: 40px;">A fir, 30 ins. diam., bears N. 61$\frac{1}{4}$° E., 23 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A decayed fir stump, size indeterminate, bears S. 57$\frac{1}{4}$° W., 25$\frac{1}{2}$ lks. dist., no marks visible.</p> <p>and the remains of the bearing tree mkd. by Markham</p> <p style="margin-left: 40px;">A root hole, bears N. 44° E., 15 lks. dist. with down maple alongside, 14 ins. diam., with healed blaze.</p> <p style="margin-left: 40px;">A root hole, bears S. 58° E., 29 lks. dist., with down fir alongside, 8 ins. diam., with scribe marks $\frac{1}{4}$ S6 BT visible on partially healed blaze.</p> <p style="margin-left: 40px;">A madrone, 14 ins. diam., bears S. 59° W., 29 lks. dist., with scribe marks $\frac{1}{4}$ S1 BT visible on bark blaze.</p> <p style="margin-left: 40px;">A fir, 6 ins. diam., bears N. 49° W., 10 lks. dist., with healed blaze.</p> <p>At the corner point</p> <p>Set a stainless post, 28 ins. long, 2$\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 31 S R 4 W R 3 W $\frac{1}{4}$ S 1 S 6 1985</p> </div> <p style="margin-left: 40px;">Deposit corner stone and iron pipe alongside, and white "DEEP-1" magnetic marker at base of stainless steel post.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 0° 04' E., Beginning a new measurement.</p> <p>Descend over NE. slope.</p>
4.05	Creek, 1 lk. wide, course N. 80° W; asc. over SW. slope.
18.40	Spur, slopes N. 50° W.: desc. over broken NE. slope.
25.785	An original line tree, a fir, 41 ins. diam., mkd. with two hack marks each on N. and S. sides. This now becomes an angle point, from which a bearing tree mkd. by person(s) unknown: