

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines, **18158**
 T. 31 S., R. 4 W., Willamette Meridism, Oregon

CHAINS

From which

A stainless steel post, 28 ins. long, 2½ ins. diam., set 22 ins. in the ground, for a reference monument, bears S. 70° W., 20 lks. dist., with brass cap mkd. RM S30 20 LKS 1985 with an arrow pointing to the corner.

A stainless steel post, 28 ins. long, 2½ ins. diam., set 22 ins. in the ground, for a reference monument, bears N. 60° W., 20 lks. dist., with brass cap mkd. RM S19 20 LKS 1985 with an arrow pointing to the corner.

S. 88° 59' W., beginning new measurement.

Descend over NW. slope.

3.34

Point for the E 1/16 sec. cor. of secs. 19 and 30.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S\ 19}{S\ 30}$
 1985

**SEE CORNER RENEWAL
 C.S. 65/44-5
 B. SHANER
 6/2002**

from which

A fir, 13 ins. diam., bears N. 42° E., 25½ lks. dist., mkd. E. 1/16 S19 BT.

A fir, 14 ins. diam., bears S. 89½° E., 26 lks. dist., mkd. E. 1/16 S30 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Descend over NW. slope.

22.75

Spur, slopes N. 50° W.; desc. over SW. slope.

23.24

The ¼ sec. cor. of secs. 19 and 30, determined from the remains of the original bearing trees:

A root hole, bears N. 53° E., 24 lks. dist., with down fir alongside, 20 ins. diam., with scribe marks ¼ S visible on decayed blaze.

A madrone root hole, surrounded with madrone shoots, bears S. 39½° E., 41 lks. dist., no marks visible.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 15 ins. in the ground, to solid rock, in a collar of stone, 3 ft. base, to top, with brass cap mkd.

T 31 S R 4 W
 ¼ $\frac{S\ 19}{S\ 30}$
 1985

from which new bearing trees