

County Surveyor's Record, Douglas County, Oregon

18171 Dependent Resurvey, Portion of the Subdivisional Lines,
T. 25 S., R 7 W., Willamette Meridian, Oregon

CHAINS	
	Ascend over broken N. slope, through heavy timber and dense undergrowth.
16.05	Ridge, bears N. and S.; desc. over NW. slope.
21.95	Dry Creek bed, 5 lks. wide, drains N. 15° W.; asc. over broken NE. slope.
37.59	The cor. of secs. 8 and 9 only, perpetuated and recorded by Vernon R. Tracy, Deputy County Surveyor, in 1970, monumented with an iron pipe, 1 in. diam., firmly set, projecting 12 ins. above ground (alongside of which is a sandstone, 10 x 7 x 4 ins. mkd. X on top,) with brass cap mkd.
	COUNTY SURVEYORS OFFICE T 25 S S 8 S 9 S 16 R 7 W 1970
	from which the remains of an original bearing tree
	A fir snag, 48 ins. diam., bears N. 49° E., 31 lks. dist., with scribe marks T25S R7W S visible on bark blaze. (Record, 29 lks.)
	and bearing trees mkd. by Tracy
	A fir, 12 ins. diam., bears S. 25° W., 6 lks. dist., with healed blaze.
	A chinquapin, 12 ins. diam., bears N. 32° W., 39 lks. dist., with illegible scribe marks visible on partially healed blaze.
	and a new bearing tree
	A fir, 8 ins. diam., bears N. 87½° E., 59 lks. dist., mkd. T25S R7W S9 BT.
	Corner is located on NE. slope, in heavy timber and dense undergrowth.
	N 0° 57' W., bet. secs. 8 and 9.
	Descend over NE. slope, through heavy timber and dense undergrowth.
12.94	Point for the witness point bet. secs. 8 and 9, at proportionate distance determined by the method of broken boundaries; there is no remaining evidence of the original corner. This point now becomes an angle point.
	Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	AP T 25 S R 7 W S 8 S 9 1985