

# County Surveyor's Record, Douglas County, Oregon

18175

Subdivision of Section 9  
T. 25 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
	<p>T 25 S R 7 W  <math>\frac{1}{4}</math> S 4            S 9            1985</p> <p>from which the original bearing trees</p> <p>A madrone, 30 ins. diam., bears S. 88 3/4° E., 165 lks. dist., with axe marks visible on decayed blaze. (Record S.88° E.)</p> <p>A fir, 72 ins. diam., bears N. 87° W., 200 lks. dist., with illegible scribe marks visible on bark blaze.</p> <p>and bearing trees mkd. by Zirpel</p> <p>A fir, 28 ins. diam., bears S. 18 1/2° E., 33 1/2 lks. dist., with healed blaze.</p> <p>A fir, 32 ins. diam., bears N. 5 3/4° W., 66 1/2 lks. dist., with healed blaze.</p> <p>Corner is located on SW. slope in light timber and moderate undergrowth.</p>
	<p>From the 1/4 sec. cor. of secs. 9 and 10, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.</p> <p style="text-align: center;">T 25 S R 7 W  <math>\frac{1}{4}</math>            S 9   S 10            1985</p> <p>from which the remains of the original bearing trees</p> <p>A decayed oak snag, size indeterminate, bears N. 65° E., 42 lks. dist., no marks visible. (Record, 44 lks.)</p> <p>A fir, 60 ins. diam., bears S. 75° W., 43 lks. dist., with healed blaze.</p> <p>and bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1958</p> <p>A fir, 22 ins. diam., bears S. 3 3/4° E., 67 lks. dist., with healed blaze.</p> <p>A fir, 16 ins. diam., bears N. 21 1/4° W., 9 lks. dist., with healed blaze.</p> <p>Corner is located on SW. slope.</p> <p>N. 89° 53' W., on the E. and W. center line of sec. 9.</p> <p>Descend over SW. slope, through light timber and moderate undergrowth.</p>
10.65	Gravelled road, 30 lks. wide, bears N. 20° E. and S. 50° W.
17.50	Creek, 10 lks. wide, course S. 20° W.; asc. over broken SE. slope.