

County Surveyor's Record, Douglas County, Oregon

18184

Subdivision of Section 18,
T. 31 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	<p>A root hole, bears S. $8\frac{1}{2}^{\circ}$ W., $67\frac{1}{2}$ lks. dist., with down fir alongside, 26 ins. diam., with healed blaze.</p> <p>and new bearing trees</p> <p>A pine, 5 ins. diam., bears S. 18° E., $96\frac{1}{2}$ lks. dist., mkd. X BT.</p> <p>A fir, 44 ins. diam., bears S. $25\frac{3}{4}^{\circ}$ W., 32 lks. dist., mkd. $\frac{1}{4}$ S13 BT on bark.</p>
19.58	<p>From the E $\frac{1}{16}$ sec. cor. of secs. 18 and 19.</p> <p>N. $1^{\circ} 55'$ E., on the N. and S. center line of the SE $\frac{1}{4}$ of sec. 18.</p> <p>Ascend over broken SE. slope.</p> <p>Point for the SE $\frac{1}{16}$ sec. cor. of sec. 18, at intersection with the E. and W. center line of the SE $\frac{1}{4}$.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., with magnetic plastic breakaway base, 28 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">SE $\frac{1}{16}$ S18 1984</p> <p>from which</p> <p>A ponderosa pine, 6 ins. diam., bears N. 38° E., 40 lks. dist., mkd. SE $\frac{1}{16}$ S18 BT.</p> <p>A ponderosa pine, 5 ins. diam., bears S. $5\frac{1}{2}^{\circ}$ E., 9 lks. dist., mkd. SE $\frac{1}{16}$ S18 BT.</p> <p>Ascend over SE. slope.</p>
22.00	Gravel road, 30 lks. wide, bears N. 60° W. and S. 60° E.
25.50	Ridge, bears N. 70° W. and S. 80° E.; descend broken NE. slope.
38.10	Dirt road, 20 lks. wide, bears N. 60° W. and S. 40° E.
39.14	The center E $\frac{1}{6}$ sec. cor. of sec. 18.
	<p>From the S $\frac{1}{16}$ sec. cor. of secs. 17 and 18.</p> <p>N. $88^{\circ} 50'$ W., on the E. and W. center line of the SE $\frac{1}{4}$ of sec. 18.</p> <p>Descend over broken SE. slope.</p>
14.55	Gravel road, 25 lks. wide, bears N. 60° W. and S. 60° E.
19.07	The SE $\frac{1}{16}$ sec. cor. of sec. 18.
	Descend over broken SE. slope.
38.15	The center S $\frac{1}{16}$ sec. cor. of sec. 18.