

County Surveyor's Record, Douglas County, Oregon

18224

Subdivision of Section 35,
T. 27 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p>A fir, 19 ins. diam., bears N. $54\frac{1}{2}^{\circ}$ E., 13 lks. dist., mkd. CW 1/16 S35 BT.</p> <p>A cedar, 13 ins. diam., bears N. $66\frac{1}{4}^{\circ}$ W., 46 lks. dist. mkd. CW 1/16 S35 BT.</p> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p> <p>Descend over broken W. slope.</p>
66.35	Gravel road, 20 lks. wide, bears N. 5° W. and S. 5° E.
80.65	The $\frac{1}{4}$ sec. cor. of secs. 34 and 35.
	<p>From the standard W 1/16 sec. cor. of sec. 35 only, on the S. bdy. of the Tp.</p> <p>N. $0^{\circ} 04'$ E., on the N. and S. center line of the SW $\frac{1}{4}$ of sec. 35.</p> <p>Across broken W. slope, through moderate timber and undergrowth.</p>
26.75	Creek, 1 lk. wide, course W.; cont. along broken W. slope.
40.14	The center W 1/16 sec. cor. of sec. 35.
	<p>N. $0^{\circ} 04'$ E., on the N. and S. center line of the NW $\frac{1}{4}$ of sec. 35.</p> <p>Ascend over broken W. slope, through moderate timber and undergrowth.</p>
8.95	Spur, slopes S. 80° W., desc. over NW slope.
16.95	Creek, 1 lk. wide, course N. 85° W.; asc. over SW slope.
20.195	<p>Point for the NW 1/16 sec. cor. of sec. 35, at intersection with the E. and W. center line of the NW $\frac{1}{4}$ of sec. 35.</p> <p>Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">NW 1/16 S 35 1985</p> <p>from which</p> <p>A cedar, 15 ins. diam., bears N. $11\frac{1}{2}^{\circ}$ E., 65 lks. dist., mkd. NW 1/16 S35 BT.</p> <p>A sugar pine, 16 ins. diam., bears S. $52\frac{3}{4}^{\circ}$ E., 39 lks. dist., mkd. NW 1/16 S35 BT.</p> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p>