

# County Surveyor's Record, Douglas County, Oregon

18255

Subdivision of Section 11,  
T. 28 S., R. 8 W., Willamette Meridian, Oregon

**CHAINS**

The corner is on a SE. slope, at a fence corner, wire fences extending N. and S. 70° W.

From the same point, the cor. of secs. 10, 11, 14, and 15, bears S. 89° 59' W., 40.33 chs. dist., perpetuated and recorded by H. L. Eppstein, Douglas County Surveyor, in 1930, from original evidence, which is no longer in existence, and further perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1957, monumented with an iron post, 1½ ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE  
T 28 S R 8 W  
10 | 11  
SEC 15 | 14  
1957

from which bearing trees mkd. by Byron

A forked oak, 12 ins. diam., bears N. 72½° E.,  
44 lks. dist., with healed blaze.

A madrone, 12 ins. diam., bears S. 67° E.,  
55 lks. dist., with healed blaze.

A fir, 23 ins. diam., bears S. 65° W., 110  
lks. dist., with healed blaze.

A fir, 13 ins. diam., bears N. 70° W., 60  
lks. dist., with healed blaze.

The corner is on a SE. slope, 5 lks. W. of a wire fence, bearing N. and S.

N. 0° 14' W., on the N. and S. center line of sec. 11.

Ascend over broken S. slope, through heavy timber and dense undergrowth.

- 0.15 Wire fence, bears E. and W.
- 17.20 Power transmission line, bears N. 20° E. and S. 20° W.
- 21.80 Power transmission line, bears N. 20° E. and S. 20° W.
- 33.00 Hill top; desc. over gentle NE. slope.
- 38.30 Slope changes; desc. over steep N. slope.
- 40.11 Point for the center ¼ sec. cor. of sec. 11, at intersection with the E. and W. center line.

Set a stainless steel post, 28 ins. ong, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 28 S R 8 W  
C ¼  
S 11  
1985

from which

A hemlock, 12 ins. diam., bears S. 87° E.,  
32 lks. dist., mkd. X BT.

A hemlock, 6 ins. diam., bears S. 29° W.,  
16 lks. dist., mkd. C¼ S11 BT.

Deposit white "DEEP-1" magnetic marker at base  
of stainless steel post.