

County Surveyor's Record, Douglas County, Oregon

18258

Subdivision of Section 11,
T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
42.10	Top of ascent, slopes N.; desc. over NW slope.
51.80	Ravine, drains NE.; asc. over broken E. slope.
60.425	Point for the center W 1/16 sec. cor. of sec. 11. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 30 ins. in the ground, with brass cap mkd.
	$C \frac{W \ 1/16}{S \ 11} C$ 1985
	from which
	A cedar, 15 ins. diam., bears N.46½° E., 50 lks. dist., mkd. CW 1/16 S11 BT.
	A fir, 8 ins. diam., bears S. 76° E., 39 lks. dist., mkd. CE 1/16 S11 BT.
	Deposit white "DEEP-1" magnetic marker at base of stainless steel post.
	The corner is located in the south track of a dirt road, 15 lks. wide, bearing E., curving NE. and W., curving NW.
	From this point, the corner of wire fences, extending E., W., and S., bears S. 41° E., 0.16 chs. dist.
	Ascend over broken E. slope.
64.90	Edge of heavy timber, bears NW. and SE.; enter scattering timber and light undergrowth.
80.55	The ¼ sec. cor. of secs. 10 and 11, perpetuated and recorded by H. L. Eppstein, Douglas County Surveyor, in 1930, from original evidence no longer in existence, further perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1957, monumented with an iron post, 1½ ins. diam., firmly set, protruding 10 ins. above the ground, with brass cap mkd.
	COUNTY SURVEYORS OFFICE T 28 S $\frac{1}{4}$ S S 10 11 R 8 W 1957
	from which a bearing tree mkd. by Eppstein
	A black oak, 48 ins. diam., bears N.26° W., 114 lks. dist., with healed blaze.
	and a bearing tree mkd. by Byron
	A fir, 20 ins. diam., bears N. 25 3/4° E., 163 lks. dist., with healed blaze.
	The corner is on the S. edge of a dirt road, 15 lks. wide, bearing E. and W., and at a fence corner, with wire fences extending N., S., E., and W.