

County Surveyor's Record, Douglas County, Oregon

18259

Subdivision of Section 11,
T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
	<p>From the center W 1/16 sec. cor. of sec. 11.</p> <p>N. 0° 08' W., on the N. and S. center line of the NW¼ of sec. 11.</p> <p>Over broken E. slope, through heavy timber and dense undergrowth.</p>
16.90	Ravine, drains E.; asc. over broken SE. slope.
19.92	<p>Point for the NW 1/16 sec. cor. of sec. 11, at intersection with the E. and W. center line of the NW 1/4.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">NW 1/16 S 11 1985</p> <p>from which</p> <p style="padding-left: 40px;">A cedar, 9 ins. diam., bears N. 32° E., 5 lks. dist., mkd. NW 1/16 S11 BT.</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears S. 69° W., 10 lks. dist., mkd. NW 1/16 S11 BT.</p> <p style="padding-left: 40px;">Deposit white "DEEP-1" magnetic marker at base of the stainless steel post.</p> <p>Ascend over broken SE. slope.</p>
36.90	Top of ascent, slopes E.; continue along E. slope.
39.86	The W 1/16 sec. cor. of secs. 2 and 11.
	<p>From the center N 1/16 sec. cor. of sec. 11.</p> <p>S. 89° 34' W., on the E. and W. center line of the NW¼ of sec. 11.</p> <p>Ascend over broken SE. slope, through heavy timber and dense undergrowth.</p>
20.09	<p>The NW 1/16 sec. cor. of sec. 11.</p> <p>Ascend over broken SE. slope.</p>
24.20	Slope changes; continue to asc. over NE. slope.
37.10	Slope changes to E.; continue ascent.
40.24	<p>The N 1/16 sec. cor. of secs. 10 and 11, monumented with an iron post, 2½ ins. diam., firmly set, protruding 5 ins. above ground, with brass cap mkd.</p> <p style="text-align: center;">N 1/16 S 10 S 11 1969</p> <p>from which the remains of the bearing trees mkd. by Roseberry, Berry, Popken, and Garrison</p> <p style="padding-left: 40px;">A fir snag, 9 ins. diam., bears S. 17½° E., 15 lks. dist., with healed blaze.</p>