

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the South Boundary, **18267**  
T. 24 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

(Restoring the survey by Harvey Gordon  
and Charles T. Gardner, in 1855)

Beginning at the cor. of secs. 1, 2, 35, and 36, on the S. bdy. of the Tp., perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1963, from original evidence no longer in existence, monumented with an iron post, 1½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S	R
S 35	S 36
S 2	S 1
T 25 S	W
1963	

from which

A fir, 9 ins. diam., bears N. 77½° E., 231 lks. dist., mkd. T24S R4W S36 BT.

A fir, 6 ins. diam., bears S. 76° E., 151 lks. dist., mkd. T25S R4W S1 BT.

A fir, 7 ins. diam., bears S. 83½° W., 654 lks. dist., mkd. T25S R4W S2 BT.

A fir, 7 ins. diam., bears N. 24° W., 231 lks. dist., mkd. T24S R4W S35 BT.

S. 89° 33' W., bet. secs. 2 and 35.

Descend over SW. slope, through cleared pasture.

4.40 Creek, 1 lk. wide, course S. 65° W.; asc. over SE slope.

9.45 Spur, slopes S. 30° W.; desc. over SW. slope.

16.20 Cantell Creek, 6 lks. wide, course S. 10° E.; asc. over broken SE. slope, also enter heavy timber and dense undergrowth, edge bears N. 10° W. and S. 10° E.

38.10 Spur, slopes S. 25° E.; desc. over broken SW. slope.

39.80 The ¼ sec. cor. of secs. 2 and 35, reestablished by proportionate measurement and recorded by F. J. Cole, Deputy County Surveyor, in 1914, and is accepted. Determined from the remains of bearing trees mkd. by Cole:

A sawed cedar stump, 34 ins. diam., bears S. 70° W., 57 lks. dist., with scribe mark B visible on opened blaze.

A sawed fir stump, 37 ins. diam., bears N. 56 3/4° W., 67 lks. dist., with healed blaze.

At the corner point.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 24 S R 4 W
¼ S 35
S 2
T 25 S R 4 W
1986