

# County Surveyor's Record, Douglas County, Oregon

18270 Dependent Resurvey of a Portion of the Subdivisional Lines  
T. 24 S., R. 4 W., Willamette Meridian, Oregon

**CHAINS**

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16  $\frac{S\ 26}{S\ 35}$   
1986

from which new bearing trees

A fir, 10 ins. diam., bears N. 38½° E., 38 lks. dist., mkd. E 1/16 S26 BT.

A chinquapin 8 ins. diam., bears S. 39¼° E., 30 lks. dist., mkd. E 1/16 S35 BT.

Deposit white "DEEP-1" magnetic marker at the base, and the iron rod alongside, the stainless steel post.

S. 88° 41' W., beginning new measurement.

Descend over NW. slope.

5.50 Ravine, drains N. 60° E.; asc. over SE. slope.

13.50 Top of ascent; thence over level land.

19.84 The ¼ sec. cor. of secs. 26 and 35, monumented with an iron post, 1½ ins. diam., firmly set, projecting 22 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S  
¼  $\frac{S\ 26}{S\ 35}$   
R 4 W  
1963

from which the remains of bearing trees mkd. by Milo E. Godfrey, Deputy County Surveyor, in 1963,

An 8 ft. high fir stump, 18 ins. diam., bears S. 33° W., 18 lks. dist., with healed double blaze.

A fir, 17 ins. diam., bears N. 12° W., 27 lks. dist., with healed blaze.

and a bearing tree mkd. by Bishop and White

A fir, 22 ins. diam., bears S. 13½° E., 179 lks. dist., with healed blaze.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, oak, dogwood, maple, and madrone; undergrowth, poison oak, arrowwood, ferns, and young timber.

Subdivision of Section 35  
T 24 S., R. 4 W., Willamette Meridian, Oregon

From the ¼ sec. cor. of secs. 2 and 35, on the S. bdy. of the Tp

N. 0° 05' E., on the N. and S. center line of sec. 35.

Ascend over broken SW. slope, changing to SE. slope, through heavy timber and dense undergrowth.