

County Surveyor's Record, Douglas County, Oregon

18282

Corrective Dependent Resurvey of
A Portion of the Subdivisional Lines,
T. 23 S., R.8 W., Willamette Meridian, Oregon

CHAINS

- A cedar, 16 ins. diam., bears N. 41¼° E., 33 lks. dist., with scribe marks ¼ S12 BT visible on open blaze.
- A hemlock, 22 ins. diam., bears S. 75 3/4° E., 73 lks. dist., with scribe marks ¼ S13 BT visible on open blaze.
- Ascend over NE. slope.
- 42.15 Dirt road, 10 lks. wide, bears N. 10° W. and S. 10° E.
- 44.55 Dirt road. 10 lks. wide, bears N. 10° W. and S. 10° E.
- 55.20 Spur, slopes N. 20° W.; desc. over W. slope.
- 61.85 Creek, 2 lks. wide, course N; asc. over NE. slope.
- 76.75 Spur, sbpes N; desc. over NW. slope.
- 80.75 The cor. of secs. 12 and 13 only, monumented with an iron post, 2½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

DOUGLAS
COUNTY SURVEYORS OFFICE
T 23 S
 | S 12
 | S 13
R 8 W BLM
1967 1967

from which the original bearing trees

- A fir, 17 ins. diam., bears S. 76° E., 97 lks. dist., with healed blaze.
- A fir, 52 ins. diam., bears S. 1° W., 25 lks. dist., with openblaze, no marks visible.

and bearing trees mkd. by Vernon Tracy, Deputy County Surveyor, in 1967

- A maple, 13 ins. diam., bears N. 78° E., 40 lks. dist., with scribe marks 23 8W S12 CS BT visible on open blaze.
- A fir, 8 ins. diam., bears S. 26° E., 42 lks. dist., with healed blaze.

Land, mountainous.
Soil, clay loam and rocky.
Timber, fir, hemlock, cedar, and oak; undergrowth, poison oak, vine maple, Oregon grape, salal, grass, and ferns.

Corrective Survey of the Subdivision of
Section Lines of Section 13,
T. 23 S., R. 8 W., Willamette Meridian, Oregon

(Correcting the survey by James E. Jelley, in 1970)

From the ¼ sec. cor. of secs. 13 and 24, monumented with an iron post, 2½ ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.