

County Surveyor's Record, Douglas County, Oregon

Corrective Survey of the Subdivision of
Section Lines of Section 13,
T. 23 S., R. 8 W., Willamette Meridian,

18283

CHAINS	
	T 23 S $\frac{1}{4}$ <u>S 13 R</u> S 24 8 W 1967
	from which the remains of the original bearing trees
	A fir stump, 36 ins. diam., bears S. 64° W., 50 lks. dist., with partially healed blaze, no marks visible.
	A fir, 31 ins. diam., bears N. 16° W., 14 lks. dist., with partially healed blaze, no marks visible.
	and bearing trees mkd. by the County Surveyor, in 1967
	a fir, 30 ins. diam., bears N. 30½° E., 55 lks. dist., with partially healed blaze, no marks visible.
	A fir, 21 ins. diam., bears S. 26 ¾° W., 117 lks. dist., with partially healed blaze., no marks visible.
	N. 0° 16' 30" E., on the N. and S. center line of sec. 13, marking and blazing the true line.
	Ascend over broken S. slope, through heavy timber and dense undergrowth
36.10	Dirt road, 20 lks. wide, bears N. 70° W. and S. 70° E.
37.55	Spur, slopes S. 70° E.; desc. over broken NE. slope.
39.705	Point for the center ¼ sec. cor. of sec. 13, at intersection with the E. and W. center line.
	From this point, the center ¼ sec. cor. of sec. 13, erroneously positioned by Jelley, bears N. 79° 08' E., 0.321 chs. dist., monumented with an iron post, firmly set in a mound of stone, 2 ft. base, to top, with brass cap mkd. and witnessed as described in the official record.
	I remove the iron post, and at the true corner point
	Reset the iron post, 10 ins. in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.
	C ¼ S 13 1986
	from which bearing trees mkd. by Jelley
	A fir, 38 ins. diam., bears S. 74½° E., 74 lks. dist., with healed blaze.
	A fir, 39 ins. diam., bears N. 36° W., 51 lks. dist., with healed blaze.
	Descend over N. slope.
44.60	Dirt road, 20 lks. wide, bears N. 70° W., and S. 70° E.
59.425	Point for the center N 1/16 sec. cor. of sec. 13.