

# County Surveyor's Record, Douglas County, Oregon

**18286** Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 23 S., R. 8 W., Willamette Meridian, Oregon

CHAINS																
	<p>and remains of bearing trees mkd. by Tracy</p> <p style="padding-left: 40px;">A hemlock stump, 6 ins. diam., bears S. 59° E., 11 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A hemlock, 9 ins. diam., bears S. 30° W., 20 lks. dist., with healed blaze.</p> <p>and a new bearing tree</p> <p style="padding-left: 40px;">A hemlock, 12 ins. diam., bears S. 30 3/4° E., 91 lks. dist., mkd. 1/4 S27 BT.</p> <p>N. 0° 16' 30" E., bet. secs. 27 and 28, marking and blazing the true line.</p> <p>Descend over NW. slope, along W. edge of logged area.</p>															
8.45	<p>Creek, 2 lks. wide, course N. 75° E.; asc. over broken SW. slope.</p>															
19.940	<p>Point for the N 1/16 sec. cor. of secs. 27 and 28.</p> <p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam. 26 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr><td style="padding: 0 10px;">N 1/16</td><td style="padding: 0 10px;">S 28</td><td style="padding: 0 10px;">S 27</td></tr> <tr><td colspan="3" style="text-align: center; padding: 0 10px;">1986</td></tr> </table> </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 23 ins. diam., bears S. 69 3/4° E., 35 lks. dist., mkd. N 1/16 S27 BT.</p> <p style="padding-left: 40px;">A fir, 9 ins. diam., bears N. 35 1/2° W., 27 lks. dist., mkd. N 1/16 S28 BT.</p> <p>Ascend over broken SW. slope.</p>	N 1/16	S 28	S 27	1986											
N 1/16	S 28	S 27														
1986																
21.75	<p>Spur, slopes N. 65° E.; desc. over broken NW. slope.</p>															
35.50	<p>Spur, slopes N. 85° E.; desc. over NW. slope.</p>															
39.880	<p>The cor. of secs. 21, 22, 27, and 28, perpetuated and recorded by Gary L. Langlitz, Deputy County Surveyor, in 1974, from original evidence no longer in existence, monumented with a brass disc, 3 1/2 ins. diam., firmly set in a drill hole in solid rock, with top mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr><td colspan="3" style="text-align: center; padding: 0 10px;">DOUGLAS COUNTY SURVEYORS OFFICE</td></tr> <tr><td colspan="3" style="text-align: center; padding: 0 10px;">T 23 S R 8 W</td></tr> <tr><td colspan="3" style="text-align: center; padding: 0 10px;">S 21   S 22</td></tr> <tr><td colspan="3" style="text-align: center; padding: 0 10px;">S 28   S 27</td></tr> <tr><td colspan="3" style="text-align: center; padding: 0 10px;">1974</td></tr> </table> </div> <p>from which the remains of bearing trees mkd. by Langlitz</p> <p style="padding-left: 40px;">A fir stump, 12 ins. diam., bears S. 69° W., 52 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A fir, 17 ins. diam., bears N. 69° W., 33 lks. dist., with healed blaze.</p> <p>and a new bearing tree</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears S. 64 3/4° E., 61 lks. dist., mkd. T23S R8W S27 BT.</p>	DOUGLAS COUNTY SURVEYORS OFFICE			T 23 S R 8 W			S 21   S 22			S 28   S 27			1974		
DOUGLAS COUNTY SURVEYORS OFFICE																
T 23 S R 8 W																
S 21   S 22																
S 28   S 27																
1974																