

# County Surveyor's Record, Douglas County, Oregon

18321

Dependent Resurvey of a Portion of the South Boundary,  
T. 30 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

(Restoring the survey by William M. Bushey, in 1893-94)

Beginning at the  $\frac{1}{4}$  sec. cor. of sec. 32 only, perpetuated and recorded by John H. Markham, Jr., Registered Engineer No. 2880, in 1959, and further perpetuated and recorded by John M. Powell, Deputy County Surveyor, in 1965, monumented with an iron pipe,  $1\frac{1}{2}$  ins. diam., firmly set, projecting 10 ins. above ground, alongside is an iron post,  $1\frac{1}{4}$  ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T30S  $\frac{1}{4}$  S32 R3W T31S 1965, from which the remains of an original bearing tree:

A fir snag, 30 ins. diam., bears N.  $71\frac{1}{2}^{\circ}$  E.,  
15 $\frac{1}{2}$  lks. dist., with healed blaze.

and bearing trees mkd. by Markham

A madrone, 14 ins. diam., bears N.  $45\frac{1}{2}^{\circ}$  E.,  
71 lks. dist., with healed blaze.

A double live oak, 14 ins. diam., bears S.  $44\frac{3}{4}^{\circ}$  E.,  
50 lks. dist., with healed double blaze.

A fir, 27 ins. diam., bears S.  $6\frac{1}{4}^{\circ}$  E., 55 lks. dist.  
with scribe marks  $\frac{1}{4}$  S32 visible on partially healed blaze.

and a new bearing tree

A cedar, 12 ins. diam., bears N.  $21\frac{1}{2}^{\circ}$  W., 42 lks. dist.,  
mkd.  $\frac{1}{4}$  S32 BT.

S.  $89^{\circ} 22'$  W., on the S. bdy. of sec. 32, marking and blazing the true line.

Descend over steep broken NW. slope, through heavy timber and moderate undergrowth.

2.33 True point for the closing cor. of secs. 5, and 6, T. 31 S., R. 3 W., hereinafter described.

Descend over steep, broken NW. slope.

6.80 Ravine, drains S.  $80^{\circ}$  W.; desc. over SW. slope.

12.50 Creek, 1 lk. wide, course N.  $40^{\circ}$  W.; asc. over broken NE. slope.

16.80 Spur, slopes N.; desc. over broken W. slope.

21.60 Dirt road, 20 lks. wide, bears N.  $20^{\circ}$  E. and S.  $20^{\circ}$  W.

22.30 East Fork Poole Creek, 5 lks. wide, course N.  $30^{\circ}$  E.; asc. over broken E. slope.

41.19 The cor. of secs. 31 and 32 only, perpetuated and recorded by John H. Markham, Jr., Registered Engineer No. 2880, in 1960, and further perpetuated and recorded by John M. Powell, Deputy County Surveyor, in 1966, monumented with an iron pin,  $\frac{3}{4}$  in. diam., firmly set, projecting 20 ins. above ground, alongside is an iron post,  $1\frac{1}{4}$  ins. diam., firmly set, projecting 18 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T30S S31 S32 S6 R3W T31S 1966, from which an original bearing tree:

A fir, 30 ins. diam., bears S.  $71\frac{1}{2}^{\circ}$  E., 45 $\frac{1}{2}$  lks. dist.,  
with opened, partially healed blaze, no marks visible.

and bearing trees mkd. by Markham

A madrone, 23 ins. diam., bears N.  $86\frac{1}{4}^{\circ}$  E., 73 lks. dist.,  
with fragmentary scribe marks visible on bark.