

# County Surveyor's Record, Douglas County, Oregon

**18328** Dependent Resurvey of a Portion of the Subdivisional Lines  
T. 31 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

COUNTY SURVEYORS OFFICE  
T 31 S R 3 W  
¼ S 29 | S 28  
1960

from which the remains of the original bearing trees

A fir, 15 ins. diam., bears N. 15° E., 21 lks. dist.,  
with healed blaze. (Record, N. 10° E.)

A rotted madrone stump, size indeterminate, bears S. 85° W.,  
52 lks. dist., no visible marks. (Record, 50 lks.)

and a bearing tree mkd. by Byron

A cedar, 25 ins. diam., bears N. 54½° W., 78 lks. dist.,  
with healed blaze.

and a bearing tree mkd. by Powell

A cedar, 10 ins. diam., bears N. 28½° E., 23½ lks. dist.,  
with healed blaze.

North, beginning new measurement.

Ascend over a broken SE. slope.

20.34 Point for the N 1/16 sec. cor. of secs. 28 and 29.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins.  
in the ground, with brass cap mkd.

N 1/16  
S 29 | S 28  
1986

from which

A cedar, 9 ins. diam., bears S. 54° E., 42 lks. dist.,  
mkd. N 1/16 S28 BT.

A cedar, 25 ins. diam., bears S. 72° W., 35½ lks. dist.,  
mkd. N 1/16 S29 BT.

Continue over SE. slope.

22.15 Spur, slopes SW.; desc. over broken NW. slope.

38.30 Dirt road, 15 lks. wide, bears S. 60° E. and W.

40.68 The cor. of secs. 20, 21, 28 and 29, perpetuated and recorded by  
Milo E. Godfrey, Deputy County Surveyor, in 1964, monumented with  
an iron post, 1½ ins. diam., firmly set, projecting 14 ins. above  
ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE  
T 31 S  
S 20 | S 21  
S 29 | S 28  
R 3 W  
1964

from which the remains of the original bearing trees

A madrone, 25 ins. diam., bears N. 37° E., 52¼ lks. dist.,  
with healed blaze. (Record, N. 39° E.)