

County Surveyor's Record, Douglas County, Oregon

18335

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 31 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

from which

A fir, 13 ins. diam., bears N. $64\frac{1}{4}^{\circ}$ E., 19 lks. dist.,
mkd. S. 1/16 S5 BT.

A fir, 12 ins. diam., bears N. $44\frac{1}{4}^{\circ}$ W., 65 lks. dist.,
mkd. S 1/16 S6 BT.

Deposit white "DEEP-1" magnetic marker at base of
stainless steel post.

Descend over broken N. slope.

21.73

An original line tree, a fir, 32 ins. diam., in good condition,
mkd. with two hacks each on N. and S. sides. This now becomes an
angle point, from which:

A stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam.,
set 24 ins. in the ground, for a reference monument,
bears S. 45° E., 15.2 lks. dist., with brass cap mkd.
RM T31S R3W S5 10 FT 1986, and an arrow pointing to
the line tree. Deposit white "Deep 1" magnetic marker
at base of stainless steel post.

A stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam.,
set 22 ins. in the ground, for a reference monument,
bears S. 45° W., 15.2 lks. dist., with brass cap mkd.
RM T31S R3W S6 10 FT 1986, and an arrow pointing to
the line tree. Deposit white "Deep 1" magnetic marker
at base of stainless steel post.

N. $0^{\circ} 02'$ E., beginning new measurement.

Descend over broken N. slope.

12.95

Creek, 1 lk. wide, course N. 65° W.; asc. over steep, broken SW.
slope.

18.19

The $\frac{1}{4}$ sec. cor. of secs. 5 and 6, perpetuated and recorded by
John H. Markham, Jr., Registered Engineer No. 2880, in 1959,
monumented with an iron pipe, $1\frac{1}{2}$ ins. diam., firmly set,
projecting 6 ins. above the ground, from which the original
bearing trees:

A fir, 25 ins. diam., bears S. $10\frac{1}{4}^{\circ}$ E., 12 lks. dist.,
with healed blaze. (Record, S. $12\frac{1}{2}^{\circ}$ E.)

A fir, 23 ins. diam., bears S. 53° W., $38\frac{1}{4}$ lks. dist.,
with healed blaze. (Record, S. $51\frac{3}{4}^{\circ}$ W.)

and bearing trees mkd. by Markham

A madrone, 8 ins. diam., bears N. $68\frac{1}{4}^{\circ}$ E., 31 lks. dist.,
with fragmentary scribe marks visible on partially
healed blaze.

A live oak, 8 ins. diam., bears S. $58\frac{1}{2}^{\circ}$ E., 37 lks. dist.,
with scribe marks S5 $\frac{1}{4}$ BT visible on partially healed
blaze.

At the corner point

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, directly over the iron pipe, with brass cap mkd.