

County Surveyor's Record, Douglas County, Oregon

18341

Subdivision of Section 28,
T. 31 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	Continue over broken N. slope.
20.75	Abandoned dirt road, 20 lks. wide, bears E. turning NE. and W.
27.80	Creek, 1 lk. wide, course NE.; asc. over broken SE. slope.
40.72	The $\frac{1}{4}$ sec. cor. of secs. 21 and 28.
<p>From the $\frac{1}{4}$ sec. cor. of secs. 27 and 28.</p> <p>S. 89° 54' W., on the E. and W. center line of sec. 28.</p> <p>Ascend over a broken SE. slope, through ehavy timber and dense undergrowth.</p>	
0.80	Gravel road, 30 lks. wide, bears N. 30° E. and S. 30° W.
11.80	Ridge, bears N. and S.; desc. over broken W. slope.
17.05	Point for the center E 1/16 sec. cor. of sec. 28.
	Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 18 ins. in the ground to solid rock, and supported in a mound of stone, 4 ft. base, to top, with brass cap mkd.
	$C \quad \frac{E \ 1/16}{S \ 28} \quad C$ <p>1986</p>
	from which
	A fir, 6 ins. diam., bears S. 80° E., 13 $\frac{1}{2}$ lks. dist., mkd. CE 1/16 S28 BT.
	A fir 12 ins. diam., bears N. 22° W., 31 $\frac{1}{2}$ lks. dist., mkd. CE 1/16 S28 BT.
	Deposit white "DEEP-1" magnetic marker at base of stainless steel post.
	Continue over broken W. slope.
34.70	Small ravine, drains NW.; continue to desc. over NW. slope.
37.30	Abandoned dirt road, 10 lks. wide, bears N. and S.
38.21	The center $\frac{1}{4}$ sec. cor. of sec. 28.
	<hr style="width: 20%; margin: 0 auto;"/>
	S. 89° 54' W., beginning new measurement.
	Descend over a broken NW. slope.
20.115	Point for the center W 1/16 sec. cor. of sec. 28.
	Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	$C \quad \frac{W \ 1/16}{S \ 28} \quad C$ <p>1986</p>
	from which
	A fir, 32 ins. diam., bears S. 62° E., 13 lks. dist., mkd. CW 1/16 S28 BT.
	A hemlock, 12 ins. diam., bears N. 52° W., 30 $\frac{1}{2}$ lks. dist., mkd. CW 1/16 S28 BT.