

# County Surveyor's Record, Douglas County, Oregon

18243

Subdivision of Section 28,  
T. 31 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	Ascend over a broken SE. slope, through scattering timber and dense undergrowth.
1.40	Gravel road, 45 lks. wide, bears N. 35° E. and S. 35° W.
7.10	Same road, 30 lks. wide, bears N. 30° E. and S. 30° W.
19.85	The SE 1/16 sec. cor. of sec. 28, established at intersection with the E. and W. center line of the SE 1/4, by William J. Ruppert, Registered Land Surveyor No. 866, in 1980, and is accepted as the corner, monumented with an aluminum post, 2 ins. diam., firmly set, projecting 6 ins. above ground, and in a collar of stone. with an aluminum cap mkd.
	T 31 S R 3 W SE 1/16 S28 PLS 866 1980
	from which bearing trees mkd. by Ruppert
	A fir, 18 ins. diam., bears S. 55° E., 201 lks. dist., with healed blaze.
	A fir, 15 ins. diam., bears S. 64½° W., 131 lks. dist., with healed blaze.
	_____
	N. 0° 26' E., beginning new measurement.
	Ascend over a SE. slope.
4.60	Ridge, bears NE. and SW.; desc. over a NW. slope.
19.85	The center E 1/16 sec. cor. of sec. 28.
	From the S 1/16 sec. cor. of secs. 27 and 28.
	S. 89° 21' W., on the E. and W. center line of the SE 1/4 of sec. 28.
	Descend over a W. slope, through scattering timber and dense undergrowth.
0.70	Ravine, drains SE.; asc. over E. slope.
5.50	Gravel road, 30 lks. wide, bears N. and S.
11.80	Spur, slopes S.; desc. over SW. slope.
15.90	Ravine, drains S.; asc. over SE. slope.
16.72	The SE 1/16 sec. cor. of sec. 28.
	_____
	S. 89° 21' W., beginning new measurement.
	Ascend over a SE. slope.
8.60	Ridge, bears NE. and SW.; desc. over a steep NW. slope.
20.78	The center S 1/16 sec. cor. of sec. 28.
	From the center W 1/16 sec. cor. of sec. 28.
	N. 0° 20' W., on the N. and S. center line of the NW 1/4 of sec. 28.
	Descend over a broken NW. slope, through scattering timber and dense undergrowth.