

# County Surveyor's Record, Douglas County, Oregon

18344

Subdivision of Section 28,  
T. 31 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
12.20	Dry creek bed, drains SW.; asc. over broken SE. slope.
13.60	Dirt road, 20 lks. wide, bears NE. and SW.
20.35	Point for the NW 1/16 sec. cor. of sec. 28, at intersection with the E. and W. center line of the NW 1/4  Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.  NW 1/16 S 28 1986  from which  A fir, 9 ins. diam., bears S. 32° W., 23 lks. dist., mkd. NW 1/16 S28 BT.  A fir, 16 ins. diam., bears N. 43° W., 24 1/2 lks. dist., mkd. NW 1/16 S28 BT.  Deposit white "DEEP-1" magnetic marker at base of stainless steel post.  Continue over SE. slope.
30.90	Dirt road, bears E. and W., on top of spur sloping E.; desc. over steep broken N. slope.
40.30	Creek, 2 lks wide, course N. from S. 30° W.
40.70	The true point for the W 1/16 sec. cor. of secs. 21 and 28, in the creek.
	From the center N 1/16 sec. cor. of sec. 28.  S. 89° 51' W., on the E. and W. center line of the NW 1/4 of sec. 28  Descend over a gentle NW. slope, through scattering timber and dense undergrowth.
0.40	Ravine, drains N.; asc. over a broken NE. slope.
8.40	Spur, slopes N.; desc. over broken NW. slope.
10.50	Abandoned dirt road, 20 lks. wide, bears N. 80° E. and S. 80° W.
13.50	Dirt road, 20 lks wide, at bottom of descent, bears N. 5° W. and S. 5° E.; asc. over a broken SE. slope.
19.99	The NW 1/16 sec. cor. of sec. 28.  Continue over broken SE. slope.
39.98	The N. 1/16 sec. cor. of secs. 28 and 29.