

# County Surveyor's Record, Douglas County, Oregon

18257

Dependent Resurvey of a Portion of the East Boundary,  
T. 30 S., R. 9 W., Willamette Meridian, Oregon

**CHAINS**

32.60

Dirt road, 20 lks. wide, bears N. 65° W. and S. 65° E.

37.30

Ravine, drains NW.; continue to desc. over NW. slope.

39.96

Point for the ¼ sec. cor of secs. 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 30 S  
R 9 W R 8 W  
¼  
S 12 | S 7  
1986

from which

A fir, 14 ins. diam., bears N. 60° E., 31½ lks. dist., mkd. ¼ S7 BT.

A fir, 12 ins. diam., bears N. 12° W., 8½ lks. dist., mkd. ¼ S12 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Continue over NW. slope.

52.70

Bridge Creek, 10 lks. wide, course W.; asc. over broken S. slope.

74.50

Emerson Ridge, bears E. and W.; desc. over N. slope.

79.92

The cor. of secs. 1, 6, 7, and 12, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1958, monumented with an iron post, 1½ ins. diam., firmly set, projecting 18 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE  
T 30 S  
R S 1 | S 6 R  
9 S 12 | S 7 8  
W W  
1958

from which the remains of the original bearing trees

A root hole, bears N. 53° E., 25 lks. dist., with a down and rotting fir, 25 ins. diam., lying alongside, with a rotted out blaze.

A fir, 35 ins. diam., bears S. 45° E., 56½ lks. dist., with healed blaze. (Record, 55 lks.)

A root hole, bears S. 55° W., 45 lks. dist., with a rotted fir of indeterminate size, lying alongside, no remaining marks.

A rotted fir stump, 38 ins. diam., bears N. 52° W., 25 lks. dist., no remaining marks. (Record, 24 lks.)

and bearing trees mkd. by Byron

A fir, 18 ins. diam., bears N. 25° E., 42 lks. dist., with healed blaze.