

County Surveyor's Record, Douglas County, Oregon

18362 Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 30 S., R. 9 W., Willamette Meridian, Oregon

CHAINS	T 30 S R 9 W $\frac{1}{4}$ $\frac{S\ 24}{S\ 25}$ 1986
	from which new bearing trees A fir, 6 ins. diam., bears N. 62½° E., 44½ lks. dist., mkd. ¼ S24 BT. A fir, 19 ins. diam., bears S. 55½° E., 36½ lks. dist., mkd. ¼ S24 BT.
	<hr style="width: 20%; margin: 0 auto;"/> N. 89° 33' W., beginning new measurement. Ascend over NE. slope, through scattering timber and dense undergrowth.
1.00	Spur, slopes N. 20° W.; desc. over broken W. slope.
17.10	Gravel road, 30 lks. wide, bears N. 50° W. and S. 50° E.
19.865	Point for the W 1/16 sec. cor. of secs. 24 and 25. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.
	W 1/16 $\frac{S\ 24}{S\ 25}$ 1986
	from which A fir, 4 ins. diam., bears N. 59° E., 20 lks. dist., mkd. X at breast height and BT at base. A fir, 10 ins. diam., bears S. 35° W., 6½ lks. dist., mkd. W 1/16 S25 BT.
	Descend over a broken SW. slope.
29.70	Twelvemile Creek, 20 lks. wide, course N.; asc. over broken E. slope.
39.73	The cor. of secs. 23, 24, 25, and 26.
SUBD of SEC. 25	From the ¼ sec. cor. of secs. 25 and 36. N. 0° 21' W., on the N. and S. center line of sec. 25. Descend over gentle NE. slope, through a logged area with dense undergrowth.
12.10	Ravine, drains E.; asc. over steep SE. slope, through heavy timber and dense undergrowth.
36.80	Abandoned dirt road, 15 lks. wide, bears NE. and SW., on spur, sloping SW.; desc. over NW. slope.
39.93	Point for the center 1/4 sec. cor. of sec. 25, at intersection with the E. and W. center line.