

County Surveyor's Record, Douglas County, Oregon

18366

T. 30 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

GENERAL DESCRIPTION

The lands included in this survey are located in Douglas County, approximately seven miles south of the town of Camas Valley, Oregon.

The area drains northwesterly by Bridge Creek and Twelvemile Creek. The elevations range from about 1200 feet above sea level to about 2000 feet above sea level. Access into the area is via logging roads branching from State Highway No. 42.

The soil is composed of rocky clay, with some exposed rock outcroppings in the higher elevations and clay loam in the creek bottoms. The timber consists of fir, hemlock, cedar, pine, yew, maple, chinquapin, oak, madrone, and alder, with undergrowth of salal, fern, poison oak, vine maple, Oregon grape, hazel, rhododendron, arrowwood, blackberry, salmonberry, huckleberry, wild rose, and young timber.

No evidence of minerals was noted in the course of the survey.

The average of a number of readings over the area gives a value of 20° E. for the mean magnetic declination, with a range of 1° due to local attractions.