

County Surveyor's Record, Douglas County, Oregon

18371

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 31 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A cedar, 12 ins. diam., bears S. 77° W., 42 lks. dist., with scribe marks 31S R8 CS bisible on partially healed blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 31 S R 8 W
S 11 | S 12
S 14 | S 13
1986

No suitable trees available in sec. 11.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

N. 0° 01' W., bet. secs. 11 and 12, marking and blazing the true line.

Descend over NW. slope, across a landslide area.

3.80 Leave slide area, enter scattering timber and dense undergrowth.

5.20 Creek, 5 lks. wide, course NE.; asc. over SE. slope.

9.50 Spur, slopes NE.; desc. over NE. slope, through heavy timber and dense undergrowth.

17.60 Union Creek, 15 lks. wide, course S. 40° E.; asc. over broken SW. slope.

19.05 Asphalt road, 40 lks. wide, bears N. 50° W. and S. 50° E.; continue over broken SW. slope, approximately 30 lks. E. of the W. edge of a clearcut logging area. The edge bears N. and S.

33.40 Gravel road, 20 lks. wide, bears E. and W.

40.08 Point for the 1/4 sec. cor. of secs. 11 and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

T 31 S R 8 W
1/4
S 11 | S 12
1986

from which

A fir, 9 ins. diam., bears S. 51° W., 54 lks. dist., mkd. 1/4 S11 BT.

A fir, 8 ins. diam., bears N. 30° W., 68½ lks. dist., mkd. X BT.

No suitable trees available in sec. 12.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

The corner is 30 lks. E. of the W. edge of clearcut logging area.

58.60 Spur, slopes W.; desc. over NW. slope.

65.90 Ravine, drains W.; asc. over SW. slope.