

County Surveyor's Record, Douglas County, Oregon

18379

Subdivision of Section 13,
T. 29 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p>From the $\frac{1}{4}$ sec. cor. of sec. 13 only, on the E. bdy. of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.</p>
	<p>T 29 S R 3 W R 2 W $\frac{1}{4}$ S 13 1976</p>
	<p>from which the remains of the original bearing trees</p> <p style="padding-left: 40px;">A fir, 35 ins. diam., bears S. $28\frac{1}{2}^\circ$ W., 101 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A rotted fir stump, 36 ins. diam., bears N. 34° W., 234 lks. dist., with a fir alongside, 36 ins. diam., with charred, healed blaze. (Record, N. 37° W., 241 lks.)</p> <p>and bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1962</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears S. 54° W., $15\frac{1}{2}$ lks. dist., with healed blaze. (Record, S. 53° W.)</p> <p style="padding-left: 40px;">A fir, 28 ins. diam., bears N. $48\frac{3}{4}^\circ$ W., $22\frac{1}{2}$ lks. dist., with healed blaze facing E.</p> <p>N. $89^\circ 10'$ W., on the E. and W. center line of sec. 13.</p> <p>Ascend over gentle NE. slope, through heavy timber and dense undergrowth.</p>
1.40	Top of ascent, slopes N.; desc. over broken NW. slope.
17.40	Gravelled road, 20 lks. wide, bears N. 45° E. and S., curving SE.; desc. over W. slope along the N. edge of a recent logged area.
19.62	Point for the center E $\frac{1}{16}$ sec. cor. of sec. 13.
	<p>Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p>
	<p>C $\frac{E\ 1/16}{S\ 13}$ C 1987</p>
	<p>from which</p> <p style="padding-left: 40px;">A fir, 4 ins. diam., bears N. 1° E., $68\frac{1}{2}$ lks. dist., mkd. X at breast height and BT at the base.</p> <p style="padding-left: 40px;">A fir stump, 20 ins. diam., 5 ft. high, bears S. 7° W., $42\frac{1}{2}$ lks. dist., mkd. CE $\frac{1}{16}$ S13 BT.</p> <p style="padding-left: 40px;">Deposit a white "Deep-1" magnetic marker at base of stainless steel post. Alongside the corner is a steel fence post of unknown origin, firmly set.</p> <p>Continue over W. slope, along the N. edge of a recent logged area</p>
21.90	Creek, 2 lks. wide, course N. 40° W.; asc. over NE. slope.
29.90	Spur, slopes N., leave edge of recent logged area, bearing E. and S.; desc. over NW. slope, through dense young timber and undergrowth.
38.80	Bottom of descent, bears NE. and SW.; thence across creek bottom land.