

County Surveyor's Record, Douglas County, Oregon

18380

Subdivision of Section 13,
T. 29 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
39.24	The center $\frac{1}{4}$ sec. cor. of sec. 13.
39.70	Days Creek, 20 lks. wide, course S. 20° W.; asc. over gentle E. slope.
43.30	Gravelled road, 20 lks. wide, bears N. 20° E. and S. 45° W.
44.30	Begin ascent over steep SE. slope.
50.30	Spur, slopes S.; desc. over SW. slope.
55.70	Ravine, drains SE.; asc. over broken E. slope.
57.72	Point for the center W $\frac{1}{6}$ sec. cor. of sec. 13.
	Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	C $\frac{W \frac{1}{16}}{S \ 13}$ C 1987
	from which
	A fir, 6 ins. diam., bears S. 70° E., 42 lks. dist., mkd. CW $\frac{1}{16}$ S13 BT.
	A fir, 20 ins. diam., bears N. 30° W., $22\frac{1}{2}$ lks. dist., mkd. CW $\frac{1}{16}$ S13 BT.
	Alongside the corner is a steel fence post of unknown origin, firmly set.
	Continue over E. slope, along the S. edge of a stand of heavy timber.
62.40	Slope changes to broken SE.; continue to ascend.
76.20	The $\frac{1}{4}$ sec. cor. of secs. 13 and 14, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.
	T 29 S R 3 W $\frac{1}{4}$ S 14 S 13 1976
	from which bearing trees mkd. by Carlson
	A fir, 8 ins. diam., bears S. 66° E., 13 lks. dist., with healed blaze.
	A fir, 50 ins. diam., bears N. 41° W., 65 lks. dist., with scribe marks $\frac{1}{4}$ S14 BT visible on a partially healed blaze. (Record, 66 lks.)
	From the center E $\frac{1}{6}$ sec. cor. of sec. 13.
	N. 0° 24' E., on the N. and S. center line of the NE $\frac{1}{4}$ of sec. 13
	Descend over broken NW. slope, along the W. edge of a stand of heavy timber, through dense young timber and undergrowth.
6.10	Ravine, drains W.; asc. over Sw. slope.
14.40	Spur, slopes N. 80° W.; desc. over NW. slope.