

# County Surveyor's Record, Douglas County, Oregon

**18406**

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 28 S., R. 8 W. Willamette Meridian, Oregon

| CHAINS |  |
|--------|--|
|        | <p style="text-align: center;">A fir, 13 ins. diam., bears N. 17½° W., 48 lks. dist., with healed blaze.</p> <p>Corner is located 6 lks. S. of wire fence, extending E. and W. S. 89° 35' W., bet. secs. 10 and 15.</p> <p>Descend over SW. slope, through moderate timber and undergrowth. Creek, 5 lks. wide, course S.; asc. over SE. slope.</p> <p>Spur, slopes S.; desc. over SW. slope.</p> <p>Creek, 5 lks. wide, course S. 30° E. from N. 55° W.; asc. over SE. slope.</p> <p>Spur, slopes N. 45° E.; desc. over W. slope.</p> <p>The cor. of secs. 9, 10, 15, and 16.</p> <p>Land, mountainous.<br/>Soil, rocky clay.<br/>Timber, fir, hemlock, cedar, madrone, oak, alder, and chinquapin, undergrowth, vine maple, salal, fern, blackberry, poison oak, and Oregon grape.</p>   |
| 40.03  | <p>N. 1° 31' E., betw. secs. 9 and 10.</p> <p>Ascend over steep, broken S. slope, through heavy timber and light undergrowth, along the W. side of a wire fence extending N. and S.</p> <p>The ¼ sec. cor. of secs. 9 and 10, monumented with an iron post, 2½ ins. diam., firmly set, projecting 9 ins. above ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 28 S R 8 W</p> <p style="margin: 0 10px;">½</p> <p>S 9   S 10</p> <p>1969</p> </div> <p>from which bearing trees mkd. by Roseberry, Berry, Popken, and Garrison</p> <p style="margin-left: 40px;">A fir, 18½ ins. diam., bears N. 28° E., 69 lks. dist., with healed blaze. (Record, 71 lks.)</p> <p style="margin-left: 40px;">A fir, 12 ins. diam., bears N. 38½° W., 120 lks. dist., with healed blaze. (Record, N. 44½° W., 118 lks.)</p> <p>Land, mountainous.<br/>Soil, rocky clay.<br/>Timber, fir, hemlock, cedar, myrtle, madrone, oak, alder, and chinquapin; undergrowth, vine maple, salal, fern, arrowwood, poison oak, blackberry, and Oregon grape.</p> |
| 18.60  | <p>From the corner of secs. 9, 10, 15, and 16.</p> <p>N. 89° 31' W., bet. secs. 9 and 16.</p> <p>Ascend along broken S. slope, along S. edge of timber.</p> <p>Spur, slopes S.; desc. over SW. slope.</p>  |
| 30.85  | <p>Burnt Mountain Access Road, paved surface, 30 lks. wide, bears N. and S., enter timber.</p>   |