

County Surveyor's Record, Douglas County, Oregon

18410

Dependent Resurvey of a Portion of the Boundaries
of Donation Land Claim No. 41,
T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
	A rotted hemlock stump, size indeterminate, bears N.25½° W. 83 lks. dist., no marks visible. and the remains of the bearing trees mkd. by Powell A white fir, 20 ins. diam., bears S. 40° W., 11 lks. dist., with healed blaze. A rotted fir stump, size indeterminate, bears N. 22° W., 77½ lks. dist., with a rotted fir log alongside, with scribe marks SE DLC 41 CS BT visible. and a new bearing tree A fir, 20 ins. diam., bears N. 20½° W., 115 lks. dist., mkd. SE DLC 41 BT.
SUBD. OF	SECTION 15
	From the ¼ sec. cor. of secs. 15 and 22. N. 0° 05' E., on the N. and S. center line of sec. 15, marking and blazing the true line. Descend over NW. slope, through heavy timber and dense undergrowth.
4.30	Creek, 20 lks. wide, course N. 85° E.; over level open land.
13.15	Tenmile Creek, 30 lks. wide, course S. 65° E.; asc. over gentle SW. slope across open pasture.
36.00	Coos Bay Wagon Road, paved surface, 30 lks. wide, bears N. 40° W. and S. 40° E.
40.09	Point for the center ¼ sec. cor. of sec. 15, at intersection with the E. and W. center line. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap mkd. T 28 S R 8 W C 1/4 S 15 1987 from which A white fir, 11 ins. diam., bears S. 42° W., 23 lks. dist., mkd. C 1/4 S 15 BT. An oak, 9 ins. diam., bears N. 77½° W., 22 lks. dist., mkd. C 1/4 S 15 BT. Deposit white "DEEP-1" magnetic marker at base of stainless steel post. Ascend over SW. slope.
44.05	Spur, slopes S. 40° W.; desc. over NW. slope.
46.05	Power transmission lines bear e. and W.
48.50	Power transmission lines, bear N. 85° W. and S. 85° E.
50.15	Creek, 3 lks. wide, course S. 45° W.; asc. over SE. slope.
53.06	Intersect the N. bdy. of Donation Land Claim No. 41.
	Point for the crossing closing co. of the N. and S. center line of sec. 15, on the N. bdy of Claim No. 41.