

# County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 15, T. 28 S., R. 8 W., **18415**  
Willamette Meridian, Oregon

CHAINS	
	Ascend over SE. slope, through heavy timber and moderate undergrowth.
4.60	Spur, slopes S. 30° W.; desc. over SW. slope.
8.45	Ravine, drains S. 20° W.; asc. over SE. slope.
12.55	Spur, slopes S.; desc. along S. slope.
16.80	Ravine, drains S. 40° E.; asc. over steep SE. slope.
19.93	The NW 1/16 sec. cor. of sec. 15, established and recorded by Don E. Garrett, Registered Land Surveyor, No. 544, in 1974, and is accepted as the corner, monumented with an iron rod, 5/8 in. diam., firmly set, projecting 5 ins. above ground.
	At the corner point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron rod, with brass cap mkd.
	NW 1/16 S 15 1987
	from which
	A white fir, 16 ins. diam., bears S. 31° E., 20 lks. dist., mkd. NW 1/16 S 15 BT.
	A fir, 9 ins. diam., bears S. 67° W., 36 lks. dist., mkd. NW 1/16 S 15 BT.
	Deposit white "DEEP-1" magnetic marker at base of stainless steel post.
	_____
	S. 89° 36' W., beginning new measurement.
	Ascend over SE. slope.
5.25	Spur, slopes S.; desc. over SW. slope.
12.30	Ravine, drains S.; asc. over steep SE. slope.
19.05	Spur, slopes S.; desc. over SW. slope
19.96	The N 1/16 sec. cor. of secs. 15 and 16.

### GENERAL DESCRIPTION

The area covered by this survey is located in Douglas County, approximately one and one-half miles northwest of Tenmile, Oregon. Access is by way of Coos Bay Wagon Road and Burnt Mountain Access Road. The area varies from flat open pastures to steep mountainous slopes. The elevation ranges from about 960 feet above sea level near the ¼ section corner of sections 15 and 22, to about 2,800 feet above sea level at the corner of sections 3, 4, 9, and 10.

The area is drained to the southeast by Tenmile Creek and its tributaries with numerous other seasonal drainages. The land is used mainly for timber production and pasture for grazing.

The soil consists mainly of rocky clay. There were no mineral deposits noted along the lines resurveyed. The timber consists of fir, hemlock, cedar, oak, madrone, myrtle, maple, chinquapin, alder, and white fir. The undergrowth consists of arrowwood, vine maple, blackberry, fern, salal, poison oak, and Oregon grape.

The average of a number of readings taken along the lines resurveyed gives a mean magnetic declination of 18° E.