

# County Surveyor's Record, Douglas County, Oregon

18418 Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 25 S., R. 1 W., Willamette Meridian, Oregon

CHAINS

A cedar snag, 10 ins. diam., bears S. 76° E., 75 lks. dist., with scribe marks T25S R1W S15 CS BT.

and bearing trees of which I have no record

A yew, 14 ins. diam., bears N. 55° E., 141 lks. dist., with scribe marks S10 BT visible on open blaze.

A sawed fir stump, 35 ins. diam., bears S. 69° W., 32 lks. dist., with scribe marks S16 BT visible on open blaze.

A root hole, bears N. 78° W., 32 lks. dist., with a a down fir alongside, 20 ins. diam., with healed blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam. 24 ins. in the ground, directly over the iron pipe, with brass cap mkd.

T 25 S	R 1 W
S 9   S 10	
S 16   S 15	
1987	

from which new bearing trees

A fir, 3 ins. diam., bears S. 33° E., 31 lks. dist., mkd. X BT.

A fir, 7 ins. diam., bears S. 81° W., 81 lks. dist., mkd. T25S R1W S16 BT.

A fir, 4 ins. diam., bears N. 20° W., 129 lks. dist., mkd. X BT.

N. 1° 51' 00" W., bet. secs. 9 and 10.

Descend over broken NW. slope, through heavy timber and dense undergrowth.

11.55 Wolverine Creek, 5 lks. wide, course N. 80° E.; asc. over SE. slope.

26.20 Spur, slopes N. 70° E.; desc. over N. slope.

34.35 Creek, 4 lks. wide, course E.; asc. over SE. slope.

35.45 Spur, slopes S. 80° E.; desc. over NE. slope.

37.75 Creek, 4 lks. wide, course S. 75° E.; asc. over SE. slope.

40.225 Point for the ¼ sec. cor. of secs. 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 25 S	R 1 W
S 9   S 10	
1987	

from which

A hemlock, 6 ins. diam., bears N. 88° E., 49 lks. dist., mkd. ¼ S10 BT.

A hemlock, 20 ins. diam., bears S. 61½° W., 23 lks. dist., mkd. ¼ S9 BT.