

County Surveyor's Record, Douglas County, Oregon

18441

Subdivision of Section 31,
T. 28 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

From the $\frac{1}{4}$ sec. cor. of secs. 31 and 32.

N. $89^{\circ} 42' 00''$ W., on the E. and W. center line of sec. 31.

Descend over NW. slope, through heavy timber and dense undergrowth.

1.35 Ravine, drains N. 20° W.; asc. over NE. slope.

5.25 Spur, slopes N. 5° W.; desc. over broken NW. slope.

9.15 Ravine, drains N. 10° W.; asc. over NE. slope.

13.80 Spur, slopes N.; desc. over NW. slope.

17.85 Ravine, drains N.; asc. over NE. slope.

19.70 Spur, slopes N.; desc. over NW. slope.

19.980 Point for the center E $\frac{1}{16}$ sec. cor. of sec. 31.

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

C $\frac{E \frac{1}{16}}{S 31}$ C

1987

from which

A cedar, 14 ins. diam., bears S. $78\frac{1}{4}^{\circ}$ E., 41 lks. dist., mkd. CE $\frac{1}{16}$ S31 BT.

A fir, 16 ins. diam., bears N. 2° W., 8 lks. dist., mkd. CE $\frac{1}{16}$ S31 BT.

Descend over NW. slope.

27.40 Ravine, drains N.; asc. over NE. slope.

33.10 Spur, slopes N.; desc. over NW. slope.

39.960 The center $\frac{1}{4}$ sec. cor. of sec. 31.

Descend over NW. slope.

44.45 Gravelled road, 20 lks. wide, bears N. 20° E. and S. 20° W.

48.15 Squaw creek, 8 lks. wide, bears N. 40° E.; asc. over broken SE. slope.

81.285 The $\frac{1}{4}$ sec. cor. of secs. 31 and 36, on the W. bdy. of the Tp., perpetuated and recorded by G. G. Stewart, Deputy County Surveyor in 1922, from original evidence no longer in existence, further perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1961, monumented with an iron post, $1\frac{1}{4}$ ins. diam., firmly set, projecting 16 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 28 S

R	7 S 36	S 31	R
W		6	W

$\frac{1}{4}$

1961