

# County Surveyor's Record, Douglas County, Oregon

28413

Subdivision of Section 31,  
T. 28 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	Ascend over broken SE. slope, through heavy timber and dense undergrowth.
16.20	Ridge, bears N. 20° E. and S. 10° W.; desc. over broken NW. slope.
19.950	The SE 1/16 sec. cor. of sec. 31.
	Descend over broken NW. slope.
22.75	Spur, slopes N. 80° W.; desc. over broken SW. slope.
34.35	Ravine, drains N. 20° W.; asc. over NE. slope.
40.000	The center S 1/16 sec. cor. of sec. 31.
<b>GENERAL DESCRIPTION</b>	
<p>The lands included in the foregoing survey are located approximately two miles southwesterly of the town of Dillard, Oregon. Access into the area is by way of a paved road along Kent Creek with gravelled and dirt roads branching from it into the area.</p> <p>The area is drained by Squaw Creek and Kent Creek, with numerous other seasonal drainages flowing into them. Elevations range from 1360 feet above sea level near the ¼ section corner of sections 6 and 31, to about 720 feet above sea level near the center ¼ section corner of section 31.</p> <p>Soil in the area is composed generally of a rocky clay with a sandy loam in the creek bottoms. Timber consists of fir, cedar, hemlock, yew, madrone, maple, chinquapin, dogwood, oak, alder, and cherry. Undergrowth is made up of salal, Oregon grape, arrowwood, hazel, rhododendron, manzanita, poison oak, blackberry, salmonberry, huckleberry, thimbleberry, vine maple, ferns, and young timber.</p> <p>There were no mineral deposits noted along the lines surveyed.</p> <p>The average of several readings throughout the area gives a value of 18° 15' E., for the mean magnetic declination. There is a range of 30' due to local attraction.</p>	