County Surveyor's Record, Douglas County, Oregon

18456 Subdivision of Section 22,
T. 21 S., R.9 W., Willamette Meridian, Oregon

CHAINS	
	From the ¼ sec. cor.of secs. 22 and 23, monumented with the original corner tree, a fir, 26 ins.diam., with healed blaze on W. side, from which the remains of an original bearing tree:
	A decayed fir stump, size indeterminate, bears S. 45° W., 10 lks. dist., with scribe marks ¼ S BT visible on open face.
	and bearing trees mkd. by Peterson
	A fir, 14 ins. diam., bears S. 67° E., 30 lks. dist., with healed blaze.
	A fir, 9 ins. diam., bears S. 75° W., 35 lks. dist., with healed blaze.
	and a local corner reported by Peterson
	An iron pipe, 2 ins. diam., firmly set, projecting 18 ins. above ground, with steel cap mkd. ¼ S22 23, bears South, 3 lks. dist.,
	and a new reference monument
	A stainless steel post, 28 ins. long, 2½ ins. diam., set 24 ins. in the ground, for a reference monument, bears N. 40½° E., 15 lks. dist., with brass cap mkd. RM ¼ S23 1987 and an arrow pointing to the corner.
	Deposit a white "Deep-1" magnetic marker at base of the stainless steel post.
	The corner is located 300 lks. N. of an old logging road, bears E. and W.
	N. 88° 27' 00" W., on the E. and W. center line of sec. 22.
	Descend along broken S. slope.
18.510	Point for the center E 1/16 sec. cor. of sec. 22.
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	C $\frac{\text{E 1/16}}{\text{S 22}}$ C 1987
	from which
	A hemlock, 12 ins. diam., bears S. 83¼°E., 24 lks. dist., mkd. CE 1/16 S22 BT.
	A fir, 17 ins. diam., bears N. 37¼° W., 42 lks. dist., mkd. CE 1/16 S22 BT.
	Descend over broken S. slope.
35.00	Vincent Creek Road, asphalt surface, 30 lks. wide, bears N. 5° E. and S. 10° E., in a curve.
36.05	Vincent Creek, 38 lks. wide, course N. 5° E.; asc. over E. slope.
37.020	The center ¼ sec. cor. of sec. 22.
	Continue ascent over E. slope.
68.25	Dirt road, 30 lks. wide, bears N. 15° E. and S. 15° W.; also begin descent over W. slope