

County Surveyor's Record, Douglas County, Oregon

18166 Dependent Resurvey of a Portion of the West Boundary,
T. 21 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

A fir, 22 ins. diam., bears N. 32° W., 15½ lks. dist.,
with healed blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins.
in the ground, directly over the iron rod, with brass cap mkd.

N 1/16
S 25 | S 30
1987

Deposit a white "DEEP-1" magnetic marker at the base of the
stainless steel post.

N. 0° 36' 00" E., beginning new measurement.

Ascend over broken SW. slope.

19.380

The cor. of secs. 19, 24, 25, and 30, reestablished by propor-
tionate measurement and recorded by Wilford N. Haines, Registered
Land Surveyor No. 239, in 1960; there is no remaining evidence
of the original corner, therefore this position is accepted
as the corner; monumented with a "T" shaped iron rod, 1 in. dia.,
firmly set, projecting 4 ins. above ground, with washer mkd.
WILFORD N HAINES 239 SURVEY POINT DRAIN ORE, from which the
bearing trees mkd. by Haines:

A fir, 12 ins. diam., bears N. 30° E., 11 lks. dist.,
with healed blaze.

A fir, 18 ins. diam., bears S. 1° E., 3 lks. dist.,
with healed blaze.

A fir, 15 ins. diam., bears S. 72° W., 27 lks. dist.,
with healed blaze.

A fir, 13 ins. diam., bears N. 56° W., 18 lks. dist.,
with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam. 22 ins. in the
ground, directly over the iron rod, with brass cap mkd.

T 21 S
R 7 W R 6 W
S 24 | S 19
S 25 | S 30
1987

N. 0° 42' 00" E., bet. secs. 19 and 24.

Ascend over broken SW. slope, through heavy timber and dense
undergrowth.

12.80

Spur, slopes W.; desc. over NW. slope.

21.80

Ravine, drains W.; asc. over SW. slope.

25.90

Dirt road, 25 lks. wide, bears NW. and SE.

30.70

Spur, slopes W.; desc. over N. slope.

36.20

Ravine, drains E.; asc. over SE slope.