

# County Surveyor's Record, Douglas County, Oregon

18470 Dependent Resurvey of a Portion of the Subdivisional Lines,  
T.21 S., R. 6 W., Willamette Meridian, Oregon

CHAINS									
	From the cor. of secs. 5, 6, 31, and 32, on the S. bdy. of the Tp. N. 0° 07' 00" W., bet. secs. 31 and 32. Ascend over SW. slope, through heavy timber and dense undergrowth.								
7.00	Gravelled road, 20 lks. wide, bears N. 30° W. and S. 30° E.								
12.20	Spur, slopes S. 80° W.; desc. over broken NE. slope.								
22.40	Dirt road, 30 lks. wide, bears E. and S. 70° W.; enter a clear-cut logging area.								
35.10	Ravine, drains N. 25° W.; asc. over SW. slope.								
39.730	Point for the $\frac{1}{4}$ sec. cor. of secs. 31 and 32 at proportionate distance; there is no remaining evidence of the original corner.  Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.								
	<table style="margin: auto; border-collapse: collapse;"> <tr><td style="padding: 0 10px;">T 21 S</td><td style="padding: 0 10px;">R 6 W</td></tr> <tr><td style="padding: 0 10px;">S 31</td><td style="padding: 0 10px;">S 32</td></tr> <tr><td colspan="2" style="text-align: center; padding: 0 10px;">1987</td></tr> </table>	T 21 S	R 6 W	S 31	S 32	1987			
T 21 S	R 6 W								
S 31	S 32								
1987									
	from which								
	<p style="margin-left: 40px;">A fir, 4 ins. diam., bears N. 88° W., 21<math>\frac{1}{2}</math> lks. dist., mkd. X at breast height and BT at the base.</p> <p style="margin-left: 40px;">A maple, 12 ins. diam., bears N. 24° W., 67 lks. dist., mkd. <math>\frac{1}{4}</math> S31 BT.</p> <p style="margin-left: 40px;">No suitable trees available in secs. 32.</p>								
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.								
	Ascend over SW. slope.								
40.90	Top of ascent, slopes NW.; desc. over NW. slope.								
44.80	Creek, 2 lks. wide, course S. 80° W.; asc. over broken SW. slope through heavy timber and dense undergrowth.								
73.10	Spur, slopes NW.; desc. over broken NE. slope.								
79.460	The cor. of secs. 29, 30, 31, and 32, monumented with an iron post, 2 $\frac{1}{2}$ ins. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd.								
	<table style="margin: auto; border-collapse: collapse;"> <tr><td style="padding: 0 10px;">T 21 S</td><td style="padding: 0 10px;">R 6 W</td></tr> <tr><td style="padding: 0 10px;">S 30</td><td style="padding: 0 10px;">S 29</td></tr> <tr><td style="padding: 0 10px;">S 31</td><td style="padding: 0 10px;">S 32</td></tr> <tr><td colspan="2" style="text-align: center; padding: 0 10px;">1979</td></tr> </table>	T 21 S	R 6 W	S 30	S 29	S 31	S 32	1979	
T 21 S	R 6 W								
S 30	S 29								
S 31	S 32								
1979									
	from which an original bearing tree								
	<p style="margin-left: 40px;">A cedar, 18 ins. diam., bears N. 85° W., 42 lks. dist., with three healed blazes.</p>								
	and bearing trees mkd. by Milo E. Godfrey, Deputy County Surveyor, in 1961								
	<p style="margin-left: 40px;">A fir, 11 ins. diam., bears N. 68° E., 58 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A hemlock, 18 ins. diam., bears S. 68° E., 41 lks. dist., with healed blaze.</p>								