

County Surveyor's Record, Douglas County, Oregon

18172

Dependent Resurvey of a Portion of the Subdivisional Lines
T. 21 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

GENERAL DESCRIPTION

The lands included in this survey are located in Douglas County, approximately five miles northwesterly from the town of Drain, Oregon.

Access is by way of logging roads branching from Oregon State Highway No. 38.

The drainage is southerly. The elevations range from 300 feet to 1700 feet above sea level.

The soil is composed of rocky clay in the higher elevations and clay loam in the creek bottoms.

The timber consists of fir, hemlock, cedar, pine, yew, maple, chinquapin, oak, madrone, and alder; with undergrowth of salal, fern, poison oak, vine maple, rhododendron, arrowwood, blackberry, salmonberry, and huckleberry.

No mineral deposits were noted during the survey.

The average of a number of readings over the area gives value of 20° 00' E. for the mean magnetic declination, with a range of 1° due to local attraction.