

County Surveyor's Record, Douglas County, Oregon

18479

Dependent Resurvey of a Portion of the North Boundary,
T 25 S, R 3 W., Willamette Meridian, Oregon

CHAINS						
	<p>A fir, 62 ins. diam., bears South, 54 lks. dist., with healed blaze.</p> <p>A rotted fir stump, size indeterminate, bears N. 44° W., 49 lks. dist., no marks visible.</p> <p>and bearing trees mkd. by Arthur Boyer, Deputy County Surveyor, in 1940</p> <p>A fir, 8 ins. diam., bears S. 29½° E., 20 lks. dist., with healed blaze.</p> <p>A fir, 10 ins. diam., bears N. 39 3/4° W., 50 lks. dist., with healed blaze.</p> <p>and bearing trees mkd. by Vernon R. Tracy, deputy County Surveyor, in 1966</p> <p>A fir, 14 ins. diam., bears N. 13° E., 27 lks. dist., with healed blaze.</p> <p>A live oak, 10 ins. diam., bears S. 46° W., 46½ lks. dist., with healed blaze.</p> <p>The corner is on a steep, rocky W. slope.</p>					
	<p>S. 88° 55' 00" W., bet. secs. 4 and 33.</p> <p>Descend over steep SW. slope, through heavy timber and dense undergrowth.</p>					
4.80	<p>Beaty Creek, 10 lks. wide, course S.; asc. over broken NE. slope.</p>					
19.805	<p>Point for the E 1/16 sec. cor. of secs. 4 and 33.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin-left: 100px;"> <table style="border: none;"> <tr> <td style="padding-right: 10px;">E 1/16</td> <td style="border-left: 1px solid black; padding-left: 5px;"> <table style="border: none; margin: 0 auto;"> <tr> <td style="text-align: center;">S 33</td> </tr> <tr> <td style="text-align: center;">S 4</td> </tr> <tr> <td style="text-align: center;">1987</td> </tr> </table> </td> </tr> </table> </div> <p>from which</p> <p style="margin-left: 40px;">A cedar, 17 ins. diam., bears N. 14¼° E., 30 lks. dist., mkd. E 1/16 S33 BT.</p> <p style="margin-left: 40px;">A hemlock, 16 ins. diam., bears S. 12° E., 27½ lks. dist., mkd. E 1/16 S4 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Ascend over broken NE. slope.</p>	E 1/16	<table style="border: none; margin: 0 auto;"> <tr> <td style="text-align: center;">S 33</td> </tr> <tr> <td style="text-align: center;">S 4</td> </tr> <tr> <td style="text-align: center;">1987</td> </tr> </table>	S 33	S 4	1987
E 1/16	<table style="border: none; margin: 0 auto;"> <tr> <td style="text-align: center;">S 33</td> </tr> <tr> <td style="text-align: center;">S 4</td> </tr> <tr> <td style="text-align: center;">1987</td> </tr> </table>	S 33	S 4	1987		
S 33						
S 4						
1987						
32.80	<p>Spur, slopes S. 50° E.; asc. over broken SE. slope.</p>					
35.45	<p>Spur, slopes S.; desc. over broken SW. slope.</p>					
39.610	<p>The ¼ sec. cor. of secs. 4 and 33, monumented with a brass tablet, 2½ ins. diam., set flush in bedrock, with cap mkd.</p> <div style="text-align: center; margin-left: 100px;"> <table style="border: none;"> <tr> <td style="padding-right: 10px;">¼</td> <td style="border-left: 1px solid black; padding-left: 5px;"> <table style="border: none; margin: 0 auto;"> <tr> <td style="text-align: center;">S 33</td> </tr> <tr> <td style="text-align: center;">S 4</td> </tr> <tr> <td style="text-align: center;">1944</td> </tr> </table> </td> </tr> </table> </div> <p>from which the remains of an original bearing tree</p>	¼	<table style="border: none; margin: 0 auto;"> <tr> <td style="text-align: center;">S 33</td> </tr> <tr> <td style="text-align: center;">S 4</td> </tr> <tr> <td style="text-align: center;">1944</td> </tr> </table>	S 33	S 4	1944
¼	<table style="border: none; margin: 0 auto;"> <tr> <td style="text-align: center;">S 33</td> </tr> <tr> <td style="text-align: center;">S 4</td> </tr> <tr> <td style="text-align: center;">1944</td> </tr> </table>	S 33	S 4	1944		
S 33						
S 4						
1944						