

County Surveyor's Record, Douglas County, Oregon

18481

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 25 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	Ascend over broken SE. slope, through heavy timber and dense undergrowth.
1.00	Gravelled road, 20 lks.wide, bears NW. and S. 30° E.
12.530	Point for the N 1/16 sec. cor.of secs. 2 and 3 Set a stianless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> N 1/16 S 3 S2 1987 </div>
	from which <div style="margin-left: 40px;"> A fir, 9 ins. diam., bears S. 75° E., 5½ lks. dist., mkd. N 1/16 S2 BT. A fir, 11 ins. diam., bears N. 38° W., 13 lks. dist., mkd. N 1/16 S3 BT. </div>
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post. Continue the ascent over SE. slope.
18.40	Slope changes to SW.; continue to asc.
24.480	The cor. of secs. 2, 3, 34, and 35, on the N. bdy. of the Tp.
	From the ¼ sec. cor. of secs. 3 and 4, perpetuated and recorded by Vernon R. Tracy, deputy County Surveyor, in 1966, monumented with an iron post, 1½ ins. diam., firmly set, projecting 15 ins. above ground, with brass cap mkd. <div style="text-align: center;"> COUNTY SURVEYORS OFFICE T 25 S ¼ S 4 S 3 R 3 W 1966 </div>
	from which bearing trees mkd. by Price <div style="margin-left: 40px;"> A fir stump, 17 ins. diam., bears N. 3° E., 91 lks. dist., with a rotted blaze. A fir, 18 ins. diam., bears N. 23° W., 129 lks. dist., with a healed blaze. </div>
	and bearing trees mkd. by Tracy <div style="margin-left: 40px;"> A fir, 25 ins. diam., bears East, 52 lks. dist., with healed blaze. A fir, 22 ins. diam., bears N. 28° W., 45½ lks. dist., with healed blaze. </div>
	N. 11° 35' 00" W., bet. secs. 3 and 4. Ascend over broken SW. slope, through heavy timber and dense undergrowth.
12.280	Point for the N 1/16 sec. cor. of secs. 3 and 4. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.