

County Surveyor's Record, Douglas County, Oregon

18487

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 25 S., R.3 W., Willamette Meridian, Oregon

CHAINS

T 25 S R 3 W
S 30 | S 29
S 31 | S 32
1943

from which the remains of original bearing trees

A root hole, bears N. 85¼° E., 96 lks.dist., with a down fir alongside, 42 ins. diam., with fragmentary scribe marks visible on bark.

A fir root crown, 65 ins. diam., bears S. 44° E., 60 lks.dist., no marks visible.

A sawed cedar stump, 40 ins. diam., bears N. 56° W., 94 lks. dist., with partially healed, rotted blaze. (Record, N. 61½° W.)

and the remains of bearing trees mkd. by Price

A fir, 43 ins. diam., bears N. 77 3/4° E., 107 lks. dist., with healed blaze. (Record, 116 lks.)

A sawed fir stump, 31 ins. diam., bears S. 50° W., 74 lks. dist., with scribe marks BT visible on partially healed blaze. (Record, S. 46° W.)

and bearing trees mkd. by Vernon R. Tracy, Deputy County Surveyor, in 1966

A fir, 11 ins. diam., bears N. 15° E., 12 lks. dist., with healed blaze.

A double maple, 12 ins. diam., bears S. 3° E., 12 lks. dist., with healed double blaze.

A fir, 10 ins. diam., bears S. 72½° W., 29 lks. dist., with healed blaze.

A madrone, 17 ins. diam., bears N. 85° W., 38 lks. dist., with healed double blaze.

The corner is located on a steep S. slope.

From the cor. of secs. 28, 29, 32, and 33.

N. 66° 57' 00" W., bet. secs. 29 and 32.

Descend over SW. slope, through heavy timber and dense undergrowth.

- 4.75 Gravelled road, 25 lks. wide, bears S. 50° E. and N. 35° W.
 - 13.40 Creek, 5 lks. wide, course S. 75° E.; continue descent over SW. slope.
 - 15.20 Creek, 5 lks. wide, course S. 20° W.; asc. over E. slope.
 - 18.20 Enter swamp, edge bears NE. and SW.
 - 20.430 Point for the E 1/16 sec. cor. of secs. 29 and 32.
- Set a stainless steel post, 28 ins. long, 2½ ins.diam., 23 ins. in the ground, with brass cap mkd.

E 1/16 S 29
 S 32
 1988