

County Surveyor's Record, Douglas County, Oregon

18439

Subdivision of Section 3,
T.25 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p>A fir stump, 25 ins. diam., bears S. 10° E., 26 lks. dist., with scribe marks S10 BT visible on rotted blaze.</p> <p>and bearing trees mkd. by Vernon R. Tracy, Deputy County Surveyor, in 1966</p> <p>A fir, 12 ins. diam., bears N. 68° E., 27 lks. dist., with healed blaze.</p> <p>A hemlock, 10 ins. diam., bears S. 30° E., 9 lks. dist., with healed blaze.</p> <p>N. 10° 59' 00" W., on the N. and S. center line of sec. 3.</p> <p>Ascend over steep, broken S. slope, through heavy timber and dense undergrowth.</p>
8.50	Spur, slopes W.; desc. over NW. slope.
10.10	Ravine, drains S. 80° W.; asc. over broken SW. slope.
14.80	Spur, slopes N. 70° W.; desc. over NW. slope.
18.70	Creek, 2 lks. wide, course S. 80° W.; continue to desc.
20.20	Creek, 2 lks. wide, course S. 60° W.; asc. over S. slope.
24.40	Top of ascent, slopes SW.; desc. over broken NW. slope.
24.990	<p>Point for the center $\frac{1}{4}$ sec. cor. of sec. 3, at intersection with the E. and W. center line.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, in a collar of stone, with brass cap mkd.</p> <p style="text-align: center;">T 25 S R 3 W C $\frac{1}{4}$ S 3 1987</p> <p>from which</p> <p>A fir, 4 ins. diam., bears S. 70° E., 14½ lks. dist., mkd. X at breast height and BT at the base.</p> <p>A fir, 20 ins. diam., bears S. 20° W., 16 lks. dist., mkd. C $\frac{1}{4}$ S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue over NW. slope.</p>
27.50	Creek, 8 lks. wide, course S. 80° W.; asc. over SW. slope.
37.350	<p>Point for the center N 1/16 sec.cor. of sec. 3.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">C N 1/16 S 3 C 1987</p> <p>from which</p>