

County Surveyor's Record, Douglas County, Oregon

18492

Subdivision of Section 3,
T. 25 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
5.30	Spur, slopes SW.; desc. over NW. slope.
9.60	Dirt road, 20 lks. wide, bears N. and S.
13.80	Creek, 3 lks. wide, course S. 15° W.; continue to desc. over broken W. slope.
19.980	The NE 1/16 sec. cor. of sec. 3. Descend over gentle W. slope.
24.20	Creek, 6 lks. wide, course S. 60° W.; asc. over broken SE. slope.
34.20	Top of ascent, bears N. and S.; across S. slope.
37.90	Begin descent over SW. slope.
39.960	The center N 1/16 sec. cor. of sec. 3.
12.320	<p>From the center W 1/16 sec. cor. of sec. 3.</p> <p>N. 11° 17' 00" W., on the N. and S. center line of the NW¼ of sec. 3.</p> <p>Ascend over broken SE. slope. through heavy timber and dense undergrowth.</p> <p>Point for the NW 1/16 sec. cor. of sec. 3, at intersection with the E. and W. center line of the NW¼.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">NW 1/16 S 3 1987</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 9 ins. diam., bears N. 71° E., 21 lks. dist., mkd. NW 1/16 S3 BT.</p> <p style="padding-left: 40px;">A cedar, 6 ins. diam., bears S. 79° E., 49 lks. dist., mkd. NW 1/16 S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue over SE. slope.</p>
16.90	Spur, slopes E.; desc. over broken NE. slope.
23.820	The W 1/16 sec. cor. of secs. 3 and 34, on the N. bdy. of the Tp.
1.90	<p>From the center N. 1/16 sec. cor. of sec. 3.</p> <p>S. 89° 16' 00" W., on the E. and W. center line of the NW¼ of sec. 3.</p> <p>Descend over SW. slope, through heavy timber and dense undergrowth.</p> <p>Creek, 1 lk. wide, course S. 40° W.; asc. over SE. slope.</p>
6.90	Spur, slopes S. 20° W.; desc. over SW. slope.
11.90	Creek, 5 lks. wide, course S. 65° E.; asc. over broken SE. slope.