

County Surveyor's Record, Douglas County, Oregon

18493

Subdivision of Section 3,
T. 25 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

20.850 The NW 1/16 sec. cor. of sec. 3.

Continue over SE. slope.

22.30 Spur, slopes S.; desc. over broken SW. slope.

41.700 The N 1/16 sec. cor. of secs. 3 and 4.

Subdivision of Section 4,
T. 25 S., R. 3 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of secs. 4 and 9, monumented with an iron post, 1 in. diam., firmly set, projecting 16 ins. above ground with brass cap mkd.

1/4 $\frac{S\ 4}{S\ 9}$
1944

from which the remains of bearing trees mkd. by Arthur Boyer, Deputy County Surveyor, in 1940

A cedar snag, 11 ins. diam., bears N. 40° E., 6 lks. dist., with scribe marks 1/4 S4 T25S R3W CS BT visible on open, double blaze.

A cedar snag, 9 ins. diam., bears S. 82° W., 11 lks. dist., with scribe marks 1/4 S9 T25S R3W CS BT visible on open, double blaze.

and the remains of bearing trees mkd. by Vernon R. Tracy, Deputy County Surveyor, in 1966

A grand fir, 20 ins. diam., bears S. 21 1/2° E., 76 lks. dist., with healed double blaze.

A cedar snag, 12 ins. diam. bears N. 25° W., 12 lks. dist., with scribe marks 1/4 S4 CS BT visible on open blaze.

and a new bearing tree

A fir, 4 ins. diam., bears N. 41 3/4° E., 71 lks. dist., mkd. 1/4 S4 BT.

N. 1° 47' 00" W., on the N. and S. center line of sec. 4.

Descend over broken NW. slope, through heavy timber and dense undergrowth.

0.40 Gravelled road, 30 lks. wide, bears N. 70° W. and S. 70° E.

25.950 The center 1/4 sec. cor. of sec. 4, established and recorded by Arthur Boyer, Deputy County Surveyor, in 1941, and is accepted as the corner, determined from the remaining bearing tree mkd. by Boyer:

A hemlock, 16 ins. diam., bears S. 63° W., 14 1/2 lks. dist., with scribe marks CEN S4 T25 R3 visible on opened blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 25 S R 3 W
C 1/4
S 4
1987