

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 9,
T. 25 S., R. 3W., Willamette Meridian, Oregon

18497

CHAINS	
	Descend over NW. slope, through heavy timber and dense undergrowth.
5.20	Creek, 1 lk. wide, course N. 55° E.; asc. over SE. slope.
6.15	Spur, slopes N. 55° E.; desc. over NE. slope.
20.205	Point for the center S 1/16 sec. cor. of sec. 9. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> C S 1/16 S 9 C 1987 </div> from which <div style="margin-left: 40px;"> A fir, 10 ins. diam., bears S. 38° W., 7 lks. dist., mkd. CS 1/16 S9 BT. A hemlock, 7 ins. diam., bears N. 18° W., 18 lks. dist., mkd. CS 1/16 S9 BT. </div> Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post. Descend over NE. slope.
23.95	Creek, 3 lks. wide, course NE.; asc. over SE. slope.
24.90	Spur, slopes E.; desc. over broken NE. slope.
34.75	Gravelled road, 20 lks. wide, bears NW. and S. 35° E.
39.00	Gravelled road, 20 lks. wide, bears N. 35° W. and S. 15° W.
40.410	Point for the center ¼ sec. cor. of sec. 9, at intersection with the E. and W. center line. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 25 S R 3 W C¼ S 9 1987 </div> from which <div style="margin-left: 40px;"> A fir, 6 ins. diam., bears S. 48½° E., 7 lks. dist., mkd. C¼ S9 BT. A hemlock, 16 ins. diam., bears S. 23½° W., 19½ lks. dist., mkd. C¼ S9 BT. </div> Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post. Descend over broken NE. slope.
47.20	Spur, slopes N. 40° E.; desc. over NW. slope.
50.90	Pike Creek, 5 lks wide, course S. 70° W.; asc. over SW. slope.
61.80	Spur, slopes NW.; desc. over NE. slope
72.95	Creek, 10 lks. wide, course N. 30° W.; asc. over SW. slope.