

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines **18514**  
T. 29 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
71.08	Ravine, drains S.; asc. over SE. slope.
72.190	The cor. of secs. 19 and 20 only.
	<p>N. 89° 04' 00" W., on the N. bdy. of sec. 19.</p> <p>Ascend over SE. slope, through heavy timber and dense undergrowth.</p> <p>1.65 Ridge, bears N. 65° E. and S. 65° W.; desc. over broken NW. slope.</p> <p>4.10 Gravel road, 20 lks. wide, bears N. 65° E. and S. 65° W.</p> <p>27.45 Same gravel road, 20 lks. wide, bears S. 50° E. and N. 50° W.</p> <p>29.40 Ravine, drains S. 10° E.; asc. over SE. slope.</p> <p>32.80 Spur, slopes S. 40° W.; desc. over NW. slope.</p> <p>37.090 Point for the <math>\frac{1}{4}</math> sec. cor. of sec. 19 only, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins long, <math>2\frac{1}{2}</math> ins. diam, 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 29 S R 4 W</p> <hr style="width: 50%; margin: auto;"/> <p><math>\frac{1}{4}</math> S 19</p> <p>1987</p> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 4 ins. diam., bears S. 72° E., 4 lks. dist., mkd. X BT.</p> <p style="margin-left: 40px;">A fir, 7 ins. diam., bears S. 30° W., 51 lks. dist., mkd. 1/4 S19 BT.</p> <p>From this point, a point established as the <math>\frac{1}{4}</math> sec. cor of sec. 18 only, and recorded by John H. Markham, Jr., Registered Engineer, No. 2880, in 1955, bears S. 40° 04' 00" E., 1.160 chs. dist., monumented with an iron pipe, 1 in. diam., firmly set, projecting 10 ins above ground, from which bearing trees mkd. by Markham:</p> <p style="margin-left: 40px;">A fir, 27 ins. diam., bears N. 53<math>\frac{1}{2}</math>° E., 15 lks. dist., with scribe marks 1/4 S18 BT visible on the bark.</p> <p style="margin-left: 40px;">A fir, 30 ins. diam., bears N. 41<math>\frac{1}{2}</math>° W., 35 lks. dist., with scribe marks 1/4 S18 BT visible on the bark.</p> <p>From this same point, a point established as the <math>\frac{1}{4}</math> sec. cor. of sec. 19 only, and recorded by John H. Markham, Jr., Registered Engineer, No. 2880, in 1955, bears S. 12° 22' 00" W, 0.880 chs. dist., monumented with an iron pipe, 1 in. diam., firmly set, projecting 5 ins. above ground, from which bearing trees mkd. by Markham:</p> <p style="margin-left: 40px;">A fir, 19 ins diam, bears S. 30° E, 25 lks dist., with healed blaze.</p> <p style="margin-left: 40px;">A sawed black oak stump, 5 ins. diam., bears N 78° E., 26<math>\frac{1}{2}</math> lks. dist., with healed blaze on log alongside stump.</p> <p>Both corners established by Markham were erroneously positioned and are not utilized in this survey.</p> <p>Ascend over broken SE slope</p>
56.35	Ridge, bears NE. and S. 30° W.; desc. over broken NW. slope.