

County Surveyor's Record, Douglas County, Oregon

18533

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 29 S., R.7 W., Willamette Meridian, Oregon

CHAINS

from which the bearing trees mkd. by Mensch

A fir, 21 ins. diam., bears S. 65° E., 38 lks. dist.,
with healed blaze.

A fir, 16 ins. diam., bears S. 23° W., 26 lks. dist.,
with healed blaze.

A fir, 16 ins. diam., bears N. 17° W., 37 lks. dist.,
with healed blaze.

and a bearing tree mkd. by James W. Byron, Deputy County
Surveyor, in 1962

A fir, 20 ins. diam., bears N. 67° E., 26½ lks. dist.,
with healed blaze.

N. 80° 23' 00" W., bet. secs. 19 and 30.

Descend over broken NW. slope, through heavy timber and moderate
undergrowth.

8.80 Spur, slopes N. 20° W.; desc. over NW. slope.

20.440 Point for the E 1/16 sec. cor. of secs. 19 and 30.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins.
in the ground, with brass cap mkd.

E 1/16 $\frac{S\ 19}{S\ 30}$
 1988

from which

A cedar, 11 ins. diam., bears N. 2° E., 18½ lks. dist.,
mkd. E 1/16 S19 BT.

A fir, 10 ins. diam., bears S. 58° W., 66 lks. dist.,
mkd. E 1/16 S30 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the
stainless steel post.

33.20 Dirt road, 20 lks. wide, bears N. 50° E. and S. 60° W.

38.40 Coarse Gold Creek, 10 lks. wide, course N. 20° E.; asc. over SE.
slope.

40.880 The ¼ sec. cor. of secs. 19 and 30, monumented with an iron post,
1 in. diam., firmly set, projecting 3 ins. above ground, with
brass cap mkd.

¼ $\frac{S\ 19}{S\ 30}$
 1924

from which the remains of the bearing trees mkd. by Mensch

A fir snag, 14 ins. diam., bears S. 14° W., 11 lks.
dist., with healed blaze. (Record, S.19° W.)

A fir, 23 ins. diam., bears N. 10° W., 8 lks.
dist., with healed blaze.

and the remains of a bearing tree mkd. by James W. Byron, Deputy
County Surveyor, in 1962