

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, **18536**  
 T. 29 S., R. 7 W., Willamette Meridian, Oregon

**CHAINS**

from which

A fir, 17 ins. diam., bears N. 8° E., 33½ lks. dist., mkd. S-N 1/64 S20 BT.

A cedar, 14 ins. diam., bears N. 82 3/4° W., 23½ lks. dist., mkd. S-N 1/64 S19 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

19.440

The N 1/16 sec. cor. of secs. 19 and 20, established by Gary L. Langlitz, Deputy County Surveyor, in 1977, and is accepted as the corner; monumented with an iron post, 1 in. diam., firmly set, projecting 5 ins. above ground, with brass cap mkd.

DOUGLAS COUNTY SURVEYOR  
 T 29 S R 7 W  
 N 1/16  
 S 19 | S 20  
 1977

from which the bearing trees mkd. by Langlitz

A cedar, 16 ins. diam., bears N. 12½° E., 30½ lks. dist., with scribe marks 1/16 S20 CS BT visible on partially healed blaze.

A pine, 20 ins. diam., bears N. 55 3/4° W., 47½ lks. dist., with scribe marks 1/16 S19 CS visible on partially healed blaze.

N. 1° 20' 00" E., beginning new measurement.

Continue over SE. slope.

19.430

The cor. of secs. 17, 18, 19, and 20, monumented with an iron post, 2 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

T 29 S R 7 W  
 S 18 | S 17  
 S 19 | S 20  
 1924

from which the remains of the original bearing trees

A rotted fir stump, 40 ins. diam., bears N. 51° E., 12 lks. dist., with rotted face.

A root hole, bears S. 42½° E., 12 lks. dist.,

A fir, 35 ins. diam., bears S. 16° W., 14 lks. dist., with healed blaze.

A rotted fir stump, 26 ins. diam., bears N. 47° W., 11 lks. dist., with rotted face.

and a bearing tree mkd. by James W. Byron, Deputy County Surveyor, in 1962.

A fir, 17 ins. diam., bears N. 50 3/4° E., 71 lks. dist., with healed blaze.

and a bearing tree mkd. by Gary L. Langlitz, Deputy County Surveyor, in 1977