

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, **18538**
T. 29 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

from which the remains of an original bearing tree

A root hole, bears N. 40° E., 29 lks. dist.,
with a down and rotted oak, 50 ins. diam.,
lying alongside, no marks remaining.

and the remains of bearing trees mkd. by Mensch

A rotted fir stump, 25 ins. diam., bears S 43° E.,
45 lks. dist., no marks remaining.

A rotted fir stump, 18 ins. diam., bears N. 8° W.,
66 lks. dist., no marks remaining.

and a bearing tree mkd. by James W. Byron, Deputy County
Surveyor, in 1957

A fir, 18 ins. diam., bears S. 63° W., 79 lks. dist.,
with healed blaze.

and a bearing tree mkd. by Glen Baughman, Registered Land
Surveyor No. 536, in 1973

A pine, 11 ins. diam., bears S 1° W., 9 lks. dist.,
with healed blaze.

and a new bearing tree

A fir, 10 ins. diam., bears N. 23° W., 21 lks. dist.,
mkd. $\frac{1}{4}$ S7 BT.

From this point, a steel rod, 5/8 in. diam., projecting 6 ins.
above ground, with an aluminum cap mkd. DOUGLAS COUNTY SURVEYORS
OFFICE, bears S. 5 3/4° E., 0.05 chs. dist.

N. 76° 22' 00" W., bet. secs. 7 and 18.

Ascend over E. slope, through heavy timber and moderate
undergrowth.

2.00 Ridge, bears N. 10° W. and S. 10° E.; desc. over broken SW. slope.

22.910 The W 1/16 sec. cor. of secs. 7 and 18, identical with Angle
Point No. 1 of Tract 49, monumented with an iron post, 1 in.
diam., firmly set, projecting 10 ins. above ground, with brass
cap mkd.

S 7	
AP 1	S 18
TR 49	
1924	

from which a bearing tree mkd. by Mensch

A fir, 24 ins. diam., bears S. 44° W., 39 lks.
dist., with healed blaze.

and a bearing tree mkd. by Gary L. Langlitz, Deputy County
Surveyor, in 1977

A fir, 8 ins. diam., bears S. 39½° E., 77 lks.
dist., with healed blaze.

and a new bearing tree

A madrone, 26 ins. diam., bears N. 24° E., 64 lks.
dist., mkd. W 1/16 S7 BT.