

# County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 19,  
T. 29 S., R. 7 W., Willamette Meridian, Oregon

18514

**CHAINS**

from which

A cedar, 13 ins. diam., bears N. 86° E., 11½ lks. dist.,  
mkd. CSS 1/64 S19 BT.

A fir, 21 ins. diam., bears S. 51½° W., 36 lks. dist.,  
mkd. CSS 1/64 S19 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the  
stainless steel post.

19.030

Point for the center S 1/16 sec. cor. of sec. 19.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins.  
in the ground, with brass cap mkd.

C  
S 1/16 | S 19  
C  
1988

from which

A fir, 15 ins. diam., bears S. 45° E., 11 lks. dist.,  
mkd. X BT.

A fir, 23 ins. diam., bears N. 78° W., 39½ lks. dist.,  
mkd. CS 1/16 S19 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the  
stainless steel post.

38.060

Point for the center ¼ sec. cor. of sec. 19, at intersection with  
the E. and W. center line.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins.  
in the ground, with brass cap mkd.

T 29 S R 7 W  
C ¼ S 19  
1988

from which

A fir, 10 ins. diam., bears N. 27½° E., 37½ lks. dist.,  
mkd. C ¼ S19 BT.

A cedar, 15 ins. diam., bears S. 20° W., 43½ lks. dist.,  
mkd. C ¼ S19 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the  
stainless steel post.

Ascend over SE. slope.

52.00

Spur, slopes E.; desc. over broken N. slope.

53.60

Gravel road, 20 lks. wide, bears N. 70° W. and S. 70° E.

54.485

Point for the center N 1/16 sec. cor. of sec. 19.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins.  
in the ground, with brass cap mkd.

C  
N 1/16 | S 19  
C  
1988

from which